

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-481

SECTION I: IDENTIFICATION

1. Name		
Present Past Other Name (if any):	: Chiranjee lal Bajaj ki haveli :	
2. Location		
LONGITUDE 75° 15 [°] E	LATITUDE 27° 36' N	
Address	Near Bissan gate, Ward No.11, Ramgarh Sehkhawati	
	: Village (village code) Post : Ramgarh District: Sikar State : Rajasthan PIN: 331024	
Approach	: The haveli is situated 45 km from Sikar and 18 km from Fatehpur bus stand and well connected by regular bus and train services upto nearest cities.	

3. Property Type

	Buildings	Religious structures	Other Structures
	Palace	Temple	Wall
	Fort	Mosque	Gateway
	Citadel	Minar	Pillar
	Govt. building	Church	Others (specify)
	Railway station	Monastery	
	Defence building	Stupa	
	Industrial building	Tomb, Mausoleum	
	Other public buildings		
\checkmark	Residential building		
	Engineering structure	Open space and related structures	Note: It is a double storied residential building. The second
	Engineering structure		
		structures	residential building. The second
	Bridge	structures Dublic square	residential building. The second storey is projecting. The entrance
	Bridge Tunnel	structures Public square Park or garden	residential building. The second storey is projecting. The entrance is a projecting foliated arch with a corbelled door. There is very little mural work on the walls. He
	Bridge Tunnel	structures Public square Park or garden Graveyard	residential building. The second storey is projecting. The entrance is a projecting foliated arch with a corbelled door. There is very little mural work on the walls. He interior has an open hall with
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well	residential building. The second storey is projecting. The entrance is a projecting foliated arch with a corbelled door. There is very little mural work on the walls. He interior has an open hall with surrounding pillared corridor. A
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well Tank	residential building. The second storey is projecting. The entrance is a projecting foliated arch with a corbelled door. There is very little mural work on the walls. He interior has an open hall with

	ABANDONED / IN USE : In use
Present	: Residence
Past	: Residence : Residence
1 451	
5. Age (Source)	
PERIOD	:
YEARS	: 20 th Century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protectio	n
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address Phone	
Phone	
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	
Any other (specify)	:
8. Statement of Significance	
Architectural	
Archaeological	
Historical	

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and D	Decorative Features
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) Urban
Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex
• Quantification Area Dimension (L x B x H	
Number of Blocks Number of Storys	(m / cm/ feet / inch) : 01
Spatial Organization Orientation Plan Allocation of Spaces	The haveli is oriented East-West and faces the West.
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	 Projecting foliated arch, cornice and brackets. Foliated arch corridor, cornice and brackets.
10. Construction Technology	
Structural System Building Techniques Material of Construction	: Indo-Persian : Arcuate : Brick, plaster
11. Condition Assessment	
In General	Good / Fair – fair
 ✓ Sign of Deterioration Serious Deterioration 	

Serious Deterioration
Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Chipping plaster, peeling paint, blackening and discolouration.

12. Threats to the Property

<	Nati
<	Neg
	Van
	Urba

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	(related to rituals / performance / factivals ato)
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
DESCRIPTION	
16. Maps/Plans/Drawings	
······································	
A- 1 • A	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS
COMMENTS	COMMENTS