

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

		Serial No.: RJ/SKR-545
4 Norma	SECTION I : IDENTIFICATIO	N
1. Name		
Present Past Other Name (if any):	: Bot Jee Ka Temple :	
2. Location		
LONGITUDE 75 ⁰ 15 ['] E	LATITUDE 27 ⁰ 36 [°] N	
Address	Near – Head Post Office, V Shakhawati	Ward No. – 13 Ramgarh
	: Village (village code) Post : Ramgar State : Rajasthan	Sikkar District: Sikar PIN: 331024
Approach	: IT is 60km from Sikar Bus services from big	and well connected by regular Cities.
3. Property Type		
Buildings	Religious structures	Other Structures
Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public buildings Residential building	 ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum 	Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellTankCave	Note: It is a old well which rests on a raised platform. Four octagonal pillars having inverted lotus type of pinnacle surround the well. A wheel is attached to the well for fetching drinking water.

4. Property Use

ABANDONED / IN USE : Abandoned
: Source of Drinking
:
20 th Century A.D.
:
:
:
on
SINGLE /MULTIPLE :
:
:
•
:
:
•
•
-
Four Octagonal pillars surround the well.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features	
* Drawings (Attach extra sheet if necessary) Urban Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex	
(m / cm/ feet / inch)	
uth and faces the South.	
otus type of pinnacle	
(m / cm/ feet / inch) uth and faces the South.	

10. Construction Technology

Structural System	:	Indo - Persian
Building Techniques	:	Brick Masonry
Material of Construction	:	Brick, Stone and rubble masonry.

11. Condition Assessment

In General

Good / Fair

Sign of Deterioration Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary)

Peeling of Plaster

12. Threats to the Property

Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS