

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-580 **SECTION I: IDENTIFICATION** 1. Name Present Gopinath Temple Past Other Name (if any): 2. Location **LONGITUDE** 75° 15' E 27⁰ 36['] N LATITUDE **Address** Ward no.-10 ramgarh shekhawati Village (village code) Post: Ramgarh District: Sikar **State**: Rajasthan **PIN**: 331024 Approach The Temple situated at ramgarh shekhawati. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is an old temple painted with pink colour. It has a painted structures foliated arch opening. Glazed Public square Bridge marble tiles in red have been used Park or garden Tunnel for flooring at the interior. A series Other engineering structure Graveyard of pointed arch adorn the internal Baolis, Well fall of the temple. The main shrine Tank has an image of Radha and Cave Krishna. Framed photographs of neural other deities are also in the

main shrine room.

4. Property Use		
	ABANDONED / IN USE: In Use	
Present Past	: Religious : Religious	
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: 17 th Century A.D. :	
	SINGLE /MULTIPLE :	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	: : : :	
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance 	: : : :	
Architectural	Dressed stone.	
Archaeological Historical Religious Any other (specify)	Erosoca diorio.	

SECTION II: DESCRIPTION

9. Physical Description and L	ecorative reatures
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) Urban
	Stand in Isolation Integral part of a Landscape / Street / Complex
Quantification Area Dimension (L x B x H) : (m / cm/ feet / inch)
Number of Blocks Number of Storys	: 01 : 01
 Spatial Organization Orientation Plan Allocation of Spaces 	: The temple is oriented East – West and faces the West. :
• Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	 Painted Foliated arch opening. Pointed arches, glazed marble tiles for flooring.
10. Construction Technology	•
Structural System Building Techniques Material of Construction 11. Condition Assessment	Indo-PersianArcuateBrick, stone and marble.
In General	Good / Fair
Sign of Deterioration Serious Deterioration Danger of Disappearance	
In Brief (Attach extra sheet if	necessary):
Well maintained	

12. Threats to the Property	
·	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS