

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-640

1. Name	SECTION I : IDENTIFICATION	N		
Present Past Other Name (if any):	: Gadaha Mandir : :			
2. Location				
LONGITUDE 75 ⁰ 15 ['] E	LATITUDE 27 ⁰ 36 [°] N			
Address	Ward no-15, near bal well.			
	: Village (village code) Post : Ringas State : Rajasthan	District : Sikar PIN: 332404		
Approach	: The mandir is situated	at Ringas.		
3. Property Type				
Buildings	Religious structures	Other Structures		
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Wall Gateway Pillar Others (specify)		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic square Park or gardenGraveyard Baolis, WellTank Cave	Note: It is a double storied building. There are 3 corbelled doors on the first storey.		

4. Property Use

✓

Religious

Any other (specify)

ABANDONED / IN USE : Present Religious 2 Religious Past : 5. Age (Source) PERIOD 2 19th Century A.D. YEARS : Precise date of Construction : Completion : Subsequent changes 2 **Destruction / Demolition** 2 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) **Private** 3 Any other (Please specify) : Name : Address : Phone : 7. Association WITH EVENTS • In History 2 In Rituals 2 In Building Construction : Any other (specify) 2 WITH PERSONS Patron 2 **Architect / Engineer** : Any other (specify) 2 8. Statement of Significance Architectural Archaeological Historical

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	: :	(m / cm/ feet / inch) 02 02
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The mandir is oriented East – West and faces the East.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	· · ·	Cornice & brackets.

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Corbelling
Material of Construction	:	Brick, plaster.

11. Condition Assessment

In General

Good / Fair

✓ Sign of Deterioration ✓ Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Broken walls; collapsed partially; blackening, discoloration.

12. Threats to the Property

\checkmark	Natu
\checkmark	Neg
\checkmark	Vano
	Urba

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS