

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-642

SECTION I: IDENTIFICATION 1. Name **Present** Chamatkareshwar Mahadev Past Other Name (if any): 2. Location LONGITUDE 75° 15' E 27⁰ 36['] N LATITUDE Address Near bal well Ward no-15 Village (village code) Post: Ringas District: Sikar State: Rajasthan **PIN**: 332404 Approach The temple is situated near bal well. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a small shrine. The structures building has projecting cornice. Bridge Public square The entrance is a corbelled Tunnel Park or garden gateway. The interior is a closed hall with a deity in the bar corner Other engineering structure Graveyard (end). Baolis, Well Tank Cave

4. Property Use		
		ABANDONED / IN USE :
Present		Policious
Past	•	Religious Religious
1 431	•	Konglodo
5. Age (Source)		
PERIOD	:	
YEARS Precise date of Construction	:	
Completion	•	
Subsequent changes	:	
Destruction / Demolition	:	
	•	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name Address	:	
Phone	:	
Thone	•	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS	_	
Patron Architect / Engineer	:	
Any other (specify)	:	
Any other (specify)	•	
8. Statement of Significance		
<u></u>		
Architectural Archaeological		
Historical		
✓ Religious	It is	s a shrine dedicated to a local deity.
Any other (specify)		•

SECTION II: DESCRIPTION

<u>9. l</u>	Physical Description and	Decora	ative Features
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban
	ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x F	Н) :	(m / om/ foot / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The temple is oriented East – West and faces the East.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : :	Corbelled doorway
10.	Construction Technology	У	
11	Structural System Building Techniques Material of Construction Condition Assessment	:	Modern Corbelling Brick, cement.
11.			,
	In General	Good Good	/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance)	
In I	Brief (Attach extra sheet i	fneces	ssary):
۱۸۱۵	II maintained		

12. Threats to the Property		
	✓	Natural
	✓	Negligence
		Vandalism
		Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS