

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-660

SECTION I: IDENTIFICATION 1. Name Present Shankar Bhagwan ka Mandir Past Other Name (if any): 2. Location LONGITUDE 75° 15' E 27⁰ 36['] N LATITUDE **Address** Baleshwar ka mohalla Ward no -14 Village (village code) Post: Ringas District: Sikar State: Rajasthan **PIN**: 332404 The Mandir is situated in baleshwar ka moholla at Approach Ringas. 3. Property Type **Other Structures Buildings** Religious structures Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Others (specify) Church Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a modern single storied structures temple. The structure has a railing running on top. The sanctum has Bridge Public square a Lingam and a carved relief on Tunnel Park or garden the wall. Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use		
		ABANDONED / IN USE :
Present Past	:	Religious
5. Age (Source)		
PERIOD YEARS	:	20 th century A.D.
Precise date of Construction Completion Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private	:	
Any other (Please specify)	:	
Name Address	:	
Phone	:	
Thomas and the second s	•	
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron 	: : : : : :	
Architect / Engineer Any other (specify) 8. Statement of Significance	:	
Architectural Archaeological ✓ Historical Religious Any other (specify)		

SECTION II: DESCRIPTION

9. 1	Physical Description and	Decora	ative reatures
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban
	Curroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x I	⊣) :	(m / om/foot / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Temple is oriented East – West and faces the East.
• An	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : :	Relief on the walls.
10.	Construction Technolog	у	
11	Structural System Building Techniques Material of Construction Condition Assessment	: : :	Modern Corbelling Brick, cement.
		Good	/ Fair
	In General	Good	<i>i</i> i ali
	Sign of Deterioration Serious Deterioration Danger of Disappearance	е	
In I	Brief (Attach extra sheet i	f neces	ssary):
Wε	II maintained		

12. Threats to the Property	
·	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS