

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-664

1. Name	SECTION I : IDENTIFICATION	N		
Present Past Other Name (if any):	: Well-1 (Bhutanath Ka I : :	Mandir)		
2. Location				
LONGITUDE 75° 15 [°] E	LATITUDE 27 ⁰ 36 ['] N			
Address	Ward no -17 Bhairo ji more mohalla			
	: Village (village code) Post : Ringas State : Rajasthan	District : Sikar PIN : 332404		
Approach	: The Mandir is situated	at Ringas.		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard ✓ Baolis, Well Tank Cave	Note: It is a well with a raised platform. 2 minars mark the mouth of the well. They have domes. The shaft is circular.		

		ABANDONED / IN USE : Abandoned
Present Past	:	Drinking water
5. Age (Source)		
PERIOD	:	
YEARS	:	19 th century A.D.
Precise date of Construction	:	-
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	•	
Any other (specify)	-	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Dellatere		

Religious
Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch)
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Well is oriented East – West and faces the East.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	Minars

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Corbelling
Material of Construction	:	Brick, cement.

11. Condition Assessment

In General

 \checkmark

Good / Fair

Sign of Deterioration Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Broken platform; chipped plaster; blackening.

12. Threats to the Property



Natural Negligence Vandalism ✓ Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS