



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-678

SECTION I: IDENTIFICATION

1. Name

Present : Shri Shankar ji Ka Mandir
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 75° 15' E

LATITUDE 27° 36' N

Address

Surani Bazaar Ward no-15.

: **Village (village code)**

Post :Shree Madhopur

District: Sikar

State : Rajasthan

PIN: 332715

Approach

: The mandir is situated insurani bazaar at shree madhopur.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is a two storied temple. The entrance is at an elevation. It has a series of foliated arches at the entrance, surmounted by a cupola with dome and pinnacle. The sanctum is in a recessed chamber.

4. Property Use

ABANDONED / IN USE : In Use

Present : Religious
Past : Religious

5. Age (Source)

PERIOD :
YEARS : 20th century A.D.
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|-------------------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input checked="" type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban / Rural Setting
Surroundings
*** Drawings** (Attach extra sheet if necessary)
Urban
Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) :
(m / cm/ feet / inch)
Number of Blocks : 01
Number of Storys : 02

- **Spatial Organization**
Orientation : The temple is oriented East – West and faces the East.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors :
Interiors : Foliated arches; cupola & dome..
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Modern
- Building Techniques** : Arcuate
- Material of Construction** : Brick, plaster.

11. Condition Assessment

In General	Good / Fair
------------	-------------

Good

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Well maintained

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS