

#### INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

### **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: RJ/SKR-693 **SECTION I: IDENTIFICATION** 1. Name **Present** Sat Kuan (Well) Past Other Name (if any): 2. Location **LONGITUDE** 75° 15' E 27° 36' N LATITUDE Address Near Garh ramgarh danta Village (village code) Post: Ramgarh Danta District: Sikar State: Rajasthan **PIN:** 332703 Approach The well is situated in Ramgarh Danta. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a well with a rounded shaft. There is a passageway to structures Public square enter from the side. It is within the Bridge fort. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present	:
Past	:
5. Age (Source)	
PERIOD	:
YEARS	: 19 <sup>th</sup> century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	
Destruction / Demolition	•
6. Ownership / Level of Protecti	on
•	SINGLE /MULTIPLE :
Public: Archaeological Survey of	:
India / State Archaeology	•
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	
In Rituals	•
In Building Construction	•
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	
Archaeological	
✓ Historical	It is part of the fort.
Religious	
Any other (specify)	

# SECTION II: DESCRIPTION

9. Physical Description and De	corative reatures
<ul> <li>Context         Urban / Rural Setting         Surroundings     </li> </ul>	* <b>Drawings</b> (Attach extra sheet if necessary) Urban
our our unit	Stand in Isolation Integral part of a Landscape / Street / Complex
Quantification     Area Dimension ( L x B x H)	: (m / cm/ feet / inch)
Number of Blocks Number of Storys	:
<ul> <li>Spatial Organization         Orientation         Plan         Allocation of Spaces     </li> </ul>	: The Well is oriented East – West and faces the East. :
ARCHITECTURAL STYLE	
Ornamentation     Exteriors     Interiors     Movable Collections	: : :
Any Other (specify)	
10. Construction Technology	
Structural System	: Indo-Persian
Building Techniques Material of Construction	<ul><li>corbelling</li><li>Brick, plaster, Mortar, stone.</li></ul>
11. Condition Assessment	
In General Go	ood / Fair
Sign of Deterioration Serious Deterioration Danger of Disappearance	
In Brief (Attach extra sheet if n	ecessary):
Growth of words; structural collap	ose of surrounding.

12. Threats to the Property		
	✓	Natural
	✓	Negligence
		Vandalism
		Urban Pressures

## **SECTION III:** REFERENCES

## 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS