

**INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS** 

Janpath, New Delhi -110 001, www.ignca.gov.in

# Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/SKR-710

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any):	: Vitkarni Ji Soni Ki Haveli :	
2. Location		
LONGITUDE 75° 15' E	LATITUDE 27 <sup>0</sup> 36 <sup>'</sup> N	
Address	<ul> <li>Near Ganesh Chowk, Ward No-11, Mohalla – Choudhary Ka, N.H-138</li> <li>Village (village code) Ramgarh Post : Danta Ramgarh District: Sikar State : Rajasthan PIN: 332703</li> </ul>	
Approach	: It is 59 km from Sikar and well connected by regular bus services.	

#### 3. Property Type

	Buildings	Religious structures	Other Structures
	Palace	Temple	Wall
	Fort	Mosque	Gateway
	Citadel	Minar	Pillar
	Govt. building	Church	<ul><li>✓ Others (specify)</li></ul>
	Railway station	Monastery	Haveli
	Defence building	Stupa	
	Industrial building	Tomb, Mausoleum	
	Other public buildings		
	<b>Decidential building</b>		
	Residential building		
<u> </u>	Engineering structure	Open space and related structures	<b>Note:</b> It is an old haveli having foliated arch opening. The vault of
	5		•
	Engineering structure	structures	foliated arch opening. The vault of
	Engineering structure Bridge	structures Dublic square	foliated arch opening. The vault of the arch has beautiful floral paintings. Flower, the paintings are faded due to age. A parapet
	Engineering structure Bridge Tunnel	structures       Public square       Park or garden	foliated arch opening. The vault of the arch has beautiful floral paintings. Flower, the paintings are faded due to age. A parapet wall is on the top of the building.
	Engineering structure Bridge Tunnel	structures         Public square         Park or garden         Graveyard	foliated arch opening. The vault of the arch has beautiful floral paintings. Flower, the paintings are faded due to age. A parapet wall is on the top of the building. The interior has a series of foliated
	Engineering structure Bridge Tunnel	structures         Public square         Park or garden         Graveyard         Baolis, Well	foliated arch opening. The vault of the arch has beautiful floral paintings. Flower, the paintings are faded due to age. A parapet wall is on the top of the building.

	ABANDONED / IN USE : In use
Present	: Residence
Past	: Residence
5. Age (Source)	
PERIOD	:
YEARS	: 20 <sup>th</sup> Century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
✓ Architectural	Dressed stone.
Archaeological	
Historical	
Religious	

Religious
Any other (specify)

SECTION II: DESCRIPTION
-------------------------

<ul> <li>Context Urban / Rural Setting Surroundings</li> </ul>			* <b>Drawings</b> (Attach extra sheet if necessary) Urban
	ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
	Quantification Area Dimension ( L x B x H)	:	
	lumber of Blocks lumber of Storys	:	(m / cm/ feet / inch 01 01
C F	Spatial Organization Drientation Plan Allocation of Spaces	:	The haveli is oriented East-West and faces the West.
	HITECTURAL STYLE		
-	Exteriors	:	The vault of the arches at the entrance has fadeo Rajasthani frecos.
N	nteriors /lovable Collections <b>Other</b> (specify)	:	Stone blocks were used for flooring purpose.

#### **10. Construction Technology**

Structural System	:	Indo-Persian
Building Techniques	:	Arcuate
Material of Construction	:	Brick and stone

# 11. Condition Assessment

In General

Good / Fair -

✓ Sign of Deterioration✓ Serious Deterioration

Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

Blackening, peeling of plaster, fading of paintings and discoloration.

# 12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS