

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR - 725 **SECTION I: IDENTIFICATION** 1. Name Present JAMA MASJID Past Other Name (if any): 2. Location 27⁰ 36' N LONGITUDE 75° 15' E LATITUDE **Address** Ward no - 14, Masjid Mohalla Village (village code) Post: Ramgarh Danta District: Sikar State: Rajasthan **PIN**: 332703 Approach The Mosque is situated in Ramgarh Danta. It is 45 KM from Sikar and well connected by regular bus services. 3. Property Type **Buildings** Religious structures **Other Structures** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a mosque within a walled compound. A staircase structures Bridge Public square leads to the main structure. There Park or garden are four minars on top of the Tunnel structure with cornice & pinnacle. Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Religious
Past	:	Religious
5. Age (Source)		
PERIOD	:	
YEARS	:	19 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)	_	
Private Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	÷	
WITH PERSONS Patron		
Architect / Engineer	:	
Any other (specify)	•	
rany canon (openany)	-	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
✓ Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9.	Physical Description and	Decora	ative Features	
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban	
	Carroanange		Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x F	H) :	(m / cm/ feet / inch)	
	Number of Blocks Number of Story's	:	01 01	
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Masjid is oriented East – West and faces the West.	
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : :		
10.	Construction Technology	y		
11	Structural System Building Techniques Material of Construction Condition Assessment	: :	Indo Persian Arcuate Brick, Plaster	
	In General	Good	/ Fair	
		Good		
	Sign of Deterioration Serious Deterioration Danger of Disappearance	e		
In Brief (Attach extra sheet if necessary):				
\/\/c	all maintained			

12. Threats to the Property	
Natural Negligence Vandalism Urban Pressures	

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS
COMMENIS	CUIVIIVIEIN I O