

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

		Serial No.: RJ/SKR - 730	
1. Name	SECTION I: IDENTIFICATION		
Present Past Other Name (if any): 2. Location	: GOPAL SAGAR (PURAI : :	NA KUAN) - WELL	
LONGITUDE 75 ⁰ 15 ['] E	LATITUDE 27 ⁰ 36 [°] N		
Address	Behind Garh, Ward no – 18, Nalawa ka mohalla		
Approach		District: Sikar PIN: 332703 Danta Ramgarh. It is 45 KM nected by regular bus services.	
3. Property Type			
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Temple	Other Structures Wall Gateway Pillar Others (specify)	
Engineering structure Bridge Tunnel Other engineering structure	structures p Public square r	Note: It is a well on a platform. 2 billars mark the mouth, joined by a rafter beam. The mouth is square. The shaft is circular.	

4. Property Use ABANDONED / IN USE : Abandoned Present 2 Past : Source of drinking water. 5. Age (Source) PERIOD 19th Century A.D. YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone ÷ 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Archaeological ✓ Historical

Religious

Any other (specify)

SECTION II: DESCRIPTION

9.	Physical Description and De	cor	ative Features
•	Context Urban / Rural Setting Surroundings		 * Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Story's	:	(m / cm/ feet / inch)
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Well is oriented East – West and faces the East.
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Ny Other (specify)	:	

10. Construction Technology

Structural System	:	Modern
Building Techniques	:	Corbelling
Material of Construction	:	Brick, Plaster

11. Condition Assessment

In General

Good / Fair

Fair

Sign of Deterioration
 Serious Deterioration
 Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening; Discoloration; Peeling paint.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs				
	(Attach list as in page 6, in case of multiple photographs)			
Photo Reference	o Reference			
CAPTION				
15. Audio / Video				
	(Related to rituals / performance / festivals etc.)			
Reference				
DESCRIPTION				
16. Maps/Plans/Drawings				
17. Listers				
NAME	NAME			
18. Reviewers				
NAME	NAME			
COMMENTS	COMMENTS			