

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-734

1. Name	SECTION I : IDENTIFICATION		
Present Past Other Name (if any):	Pratap Singh Ki Haveli		
Other Name (il any).	•		
2. Location			
LONGITUDE 75 ⁰ 15 ['] E	LATITUDE 27 ⁰ 36 [°] N		
Address	Ward No-5, Near Bus stand, Rajputo Ka Mohalla		
	: Village (village code) Ramgarh Post : Danta Ramgarh State : Rajasthan PIN: 332703		
Approach	: It is 59 km from Sikar and well connected by regular bus services.		

3. Property Type



4. Property Use ABANDONED / IN USE : Present Residence 2 Residence Past • 5. Age (Source) PERIOD 20th Century A.D. YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone ÷ 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Multiple arch opening. \checkmark Archaeological Historical

Religious

Any other (specify)

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features					
•	Context Urban / Rural Setting Surroundings		 * Drawings (Attach extra sheet if necessary) Rural Setting Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex 			
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	: : :	(m / cm/ feet / inch) 02 02			
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The haveli is oriented East-West and faces the West.			
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		It has a multiple arch opening. A series of foliated arches and circular pillars.			

10. Construction Technology

Structural System Building Techniques Material of Construction	-	Indo-Persian Arcuate Brick and Stone
Material of Construction	:	Brick and Stone

11. Condition Assessment

In General

Good / Fair -

✓ Sign of Deterioration
 ✓ Serious Deterioration
 Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Discolouration and peeling of plaster.

12. Threats to the Property

\checkmark	Na
\checkmark	Ne
\checkmark	Va
	Url

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS