

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR - 807 SECTION I : IDENTIFICATION 1. Name		
Present Past Other Name (if any): 2. Location	: Ganga Sagar ka Manc : :	lir
LONGITUDE 75° 15' E	LATITUDE 27 ⁰ 36 ['] N	
Address	ddress Near Danta bus stand	
Approach		District: Sikar PIN: 332703 near Danta bus stand at Danta. rell connected by regular bus
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures✓TempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellTankCave	Note: It is a small temple having foliated arch opening. The exterior face of the temple is being used for commercial purpose. The interior walls of the temple are adorned with lime plaster. A Chhatri having an inverted lotus type of pinnacle is in the interior.

4. Property Use

	ABANDONED / IN USE : In use	
Present Past	Religious	
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	20 th century AD	
6. Ownership / Level of Protection		
	SINGLE /MULTIPLE :	
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)		
Private		
Any other (Please specify)		
Name Address		
Phone		
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 		
8. Statement of Significance		
 Architectural Archaeological Historical Religious Any other (specify) 	ressed stone	

•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban	
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:		
	Number of Blocks		(m / cm/ feet / inch 01	
	Number of Story's	:	02	
	Spatial Organization			
	Orientation	:	The Mandir is oriented East – West and faces the East.	
	Plan	:		
	Allocation of Spaces	:		
١F	CHITECTURAL STYLE			
•	Ornamentation			
	Exteriors	:	It has a foliated arch opening.	
	Interiors	:	The walls are adorned with lime plaster. It has a Chhat having an inverted lotus type of pinnacle.	
	Movable Collections	:		
٩r	y Other (specify)	:		

Structural System	:	Indo Persian
Building Techniques	:	Arcuate
Material of Construction	:	Brick and stone

11. Condition Assessment

In General	Good / Fair Good		
Sign of Deterioration			

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS