

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

1. Name	SECTION I : IDENTIFICATION	Serial No.: RJ/SKR - 818
Present Past Other Name (if any):	: Santosh Devi Agrawal k :	i haveli
2. Location		
LONGITUDE 75 ⁰ 15 ['] E	LATITUDE 27 ⁰ 36 ['] N	
Address	Danta Ramgarh	
Approach		District: Sikar PIN: 332703 Danta. It is 65 KM from Sikar regular bus services from big
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Temple	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures I Public square Park or garden	Note: It is a dilapidated Haveli having foliated arch opening. The vault of the arch has a coating of lime plaster.

4. Property Use ABANDONED / IN USE : Present Residence 2 Residence Past • 5. Age (Source) PERIOD 19th century AD YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone ÷ 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Dressed stone \checkmark Archaeological Historical

Religious

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban		
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)	
	Number of Blocks Number of Story's	:	01 01	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The haveli is oriented East – West and faces the West.	
<u>AF</u> •	RCHITECTURAL STYLE Ornamentation Exteriors Interiors	:	It has foliated arch opening. The door at the entrance is studded with pointed metal knobs.	
Ar	Movable Collections ny Other (specify)	:		

10. Construction Technology

Structural System	:	Indo Persian
Building Techniques	:	Arcuate
Material of Construction	:	Brick and stone

11. Condition Assessment

In General

Good / Fair

Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Peeling of plaster and discoloration.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS