

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

<u> </u>	<u> </u>			
Documentation format for Archaeological / Heritage Sites / Monuments				
1. Name	SECTION I: IDENTIFICATION	Serial No.: RJ/SKR - 832		
Present Past Other Name (if any): 2. Location	: Hari Prasad Agrawal ki : :	Haveli		
LONGITUDE 75° 15' E Address	LATITUDE 27 ⁰ 36 ['] N Ward no – 10, Danta			
Approach 3. Property Type		District: Sikar PIN: 332703 nayon ki gali at Danta. It is 45 ell connected by regular bus		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify) Haveli		
Engineering structure Bridge Tunnel Other engineering structure	<u>str</u> uctures	Note: It is a Haveli having foliated arch opening. The exterior walls are adorned with lime plaster.		

4. Property Use		
		ABANDONED / IN USE :
Present Past	:	Residence Residence
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion	: : : : : : : : : : : : : : : : : : : :	20 th century AD
Subsequent changes Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private	:	
Any other (Please specify) Name	:	
Address	:	
Phone	:	
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: : : : : : : : : : : : : : : : : : : :	
8. Statement of Significance		
✓ Architectural Archaeological Historical Religious Any other (specify)	Dre	essed stone

SECTION II: DESCRIPTION

9.	Physical Description and I	Decora	ative Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban
	ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x F	H) :	(m / am/fact / inch)
	Number of Blocks Number of Story's	:	(m / cm/ feet / inch) 02 01
•	Spatial Organization Orientation	:	The haveli is oriented North – South and faces the North.
	Plan Allocation of Spaces	:	North.
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : : : : : : : : : : : : : : : : : :	The walls are coated with lime plaster.
10.	. Construction Technology	y	
11	Structural System Building Techniques Material of Construction Condition Assessment	: : :	Indo Persian Arcuate Brick and stone
11.			
	In General	Good Good	/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance)	
In	Brief (Attach extra sheet if	fneces	ssary):
Pe	eling of plaster.		

12. Threats to the Property	
Natural Negligence Vandalism Urban Pressures	

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
0.1	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
TVAINE	White
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS