

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

4 Nove	SECTION I : IDENTIFICATION	Serial No.: RJ/SKR - 835
1. Name Present Past Other Name (if any): 2. Location	: Sarwan Jee Jangir ki ha : :	veli
LONGITUDE 75 ⁰ 15 ['] E	LATITUDE 27 ⁰ 36 ['] N	
Address	Near the Fort, ward no - 24	
Approach	 Village (village code) Post : Danta State : Rajasthan The haveli is situated in and well connected by read 	District: Sikar PIN: 332703 a Danta. It is 45 KM from Sikar egular bus services.
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Temple	Other Structures Wall Gateway Pillar Others (specify) Haveli
Engineering structure Bridge Tunnel Other engineering structure	structures Public square Park or garden	Note: It is a dilapidated structure. The boundary wall is damaged. It has a small wooden door at the entrance. The building complex is cluttered with stones and bricks.

4. Property Use ABANDONED / IN USE : Present Residence 2 Residence Past • 5. Age (Source) PERIOD 19th century AD YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone : 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Archaeological Historical Religious

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks	:	(m / cm/ feet / inch) 01	
•	Number of Story's Spatial Organization Orientation Plan Allocation of Spaces	:	01 The haveli is oriented East – West and faces the East.	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	The haveli is dilapidated. It has a series of foliated arches at the interior.	

10. Construction Technology

Structural System	:	Indo Persian
Building Techniques	:	Arcuate
Material of Construction	:	Brick and stone masonry

11. Condition Assessment

In General

Good / Fair

Sign of Deterioration ✓ Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dilapidated

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS