

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

1. Name	SECTION I: IDENTIFICATION	Serial No.: RJ/SKR - 865
Present Past Other Name (if any):	: Unknown haveli :	
2. Location		
LONGITUDE 75 ⁰ 15 ['] E	LATITUDE 27 ⁰ 36 ['] N	
Address	Ward no – 24	
Approach		District: Sikar PIN: 332703 Danta Ramgarh. It is 45 KM acted by regular bus services
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildings✓Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures dil	ote: It is an old haveli in a apidated state. The exterior alls are damaged. It has a series foliated arches at the interior.

4. Property Use ABANDONED / IN USE : Present Locked 2 Residence Past • 5. Age (Source) PERIOD 19th century AD YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone 2 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Archaeological Historical Religious

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Story's	:	(m / cm/ feet / inch) 01 01	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The haveli is oriented East – West and faces the east.	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		A series of painted arches at the interior are dilapidated.	

10. Construction Technology

Structural System Building Techniques		Indo Persian Arcuate
Material of Construction	:	Brick and stone

11. Condition Assessment

In General	Good / Fair Good	
	0004	

✓ Sign of Deterioration
✓ Serious Deterioration
Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained.

12. Threats to the Property

✓ Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs			
	(Attach list as in page 6, in case of multiple photographs		
Photo Reference			
CAPTION			
15. Audio / Video			
	(Related to rituals / performance / festivals etc.)		
Reference			
DESCRIPTION			
16. Maps/Plans/Drawings			
17. Listers			
NAME	NAME		
18. Reviewers			
NAME	NAME		
COMMENTS	COMMENTS		