

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR - 871 **SECTION I: IDENTIFICATION** 1. Name Present Laturam Chajarimal Pansari ki haveli 2 Past 2 Other Name (if any): : 2. Location LONGITUDE 75° 15' E 27⁰ 36['] N LATITUDE Address Main market, Ward no - 21 Village (village code) : **Post :** Danta Ramgarh District: Sikar State : Rajasthan **PIN:** 332703 Approach The haveli is situated in main market at Danta 1 Ramgarh. It is 46 KM from Sikar and well connected by regular bus services. 3. Property Type **Buildings Religious structures Other Structures** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings \checkmark **Residential building** Note: It is a dilapidated structure. Engineering structure Open space and related structures The complex is cluttered with Bridge Public square debris and bricks. Park or garden Tunnel Other engineering structure Graveyard Baolis, Well

Tank Cave

4. Property Use

		ABANDONED / IN USE : Abandoned
Present	:	
Past	:	Residence
5. Age (Source)		
PERIOD	:	
YEARS	:	19 th century AD
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protectio	<u>n</u>	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological Historical		
Religious		

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) Urban			
	Stand in Isolation Integral part of a Landscape / Street / Complex			
 Quantification Area Dimension (L x B x H) Number of Blocks Number of Story's 	: (m / cm/ feet / inch) :			
• Spatial Organization Orientation Plan Allocation of Spaces	The haveli is oriented East – West and faces the west.			
ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	 It is a dilapidated structure. Damaged foliated arches can be seen at the interior. 			

10. Construction Technology

Structural System Building Techniques Material of Construction		Indo Persian Arcuate Briak, stopp and marble
Material of Construction	:	Brick, stone and marble.

11. Condition Assessment

In General	Good / Fair Good	

✓ Sign of Deterioration
 ✓ Serious Deterioration
 Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dilapidated.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS