

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

1. Name	SECTION I: IDENTIFICATION	Serial No.: RJ/SKR - 889
Present Past Other Name (if any):	: Shah Alamgir ka Masjid :	
2. Location		
LONGITUDE 75° 15' E	LATITUDE 27 ⁰ 36 ['] N	
Address	Khath Shyam jee, ward no – 8	3
Approach	-	District: Sikar PIN: 332602 Khath Shyam jee. It is 45 KM ected by regular bus services
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Temple	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structureswithPublic squareardPark or gardenand	bte: It is a mosque embellished th beautiful paintings and chitectural pattern. The walls d floors are adorned with glazed arble tiles.

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	Religious
Past	:	Religious
5. Age (Source)		
PERIOD	:	
YEARS	:	16 th century AD
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protecti	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)		
Name		
Address		
Phone	÷	
7. Association		
WITH EVENTS		
In History		
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS	•	
Patron	•	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
✓ Architectural	Dre	essed stone
Archaeological		
Historical		
Peligious		

Religious
Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
	* Drawings (Attach extra sheet if necessary) Urban		
	Stand in Isolation Integral part of a Landscape / Street / Complex		
:	(m / cm/ feet / inch)		
:	01 01		
:	The masjid is oriented East – West and faces the East.		
:	The dome is adorned with an inverted lotus type of pinnacle. The walls and floors are embellished with glazed marble tiles.		

10. Construction Technology

Structural System	:	Indo Persian
Building Techniques	:	Arcuate
Material of Construction	:	Brick and stone

11. Condition Assessment

In General	
------------	--

Good / Fair Good

Si	gn c	of De	tei	rior	ation	
~		-				

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS