

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

1. Name	SECTION I: IDENTIFICATION	Serial No.: RJ/SKR - 891
Present Past Other Name (if any):	: Sita ram jee ka Temple :	
2. Location		
LONGITUDE 75 ⁰ 15 ['] E	LATITUDE 27 ⁰ 36 [°] N	
Address	Bihari das jee ka mandir, war	d no – 11
Approach		District: Sikar PIN: 332602 Khath. It is 45 KM from Sikar egular bus services from big
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Image: Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structuresfolPublic squarewaPark or gardenplaGraveyardof	ote: It is a small temple having liated arch entrance. The interior alls are cladded with lime aster. The walls have a number alcoves. The door of the main rine is painted blue.

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	Religious
Past	:	Religious
5. Age (Source)		
PERIOD	:	
YEARS	:	14 th century AD
Precise date of Construction	:	,
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protecti	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name		
Address		
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS	-	
Patron	-	
Architect / Engineer		
Any other (specify)	-	
	•	
8. Statement of Significance		
✓ Architectural	Fre	esh dressed stone
Archaeological		
Historical		

Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban	
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks	:	(m / cm/ feet / inch)
	Number of Story's	:	01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented East – West and faces the West.
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : : : : : : : : : : : : : : : : : :	It has a foliated arch opening. The walls are cladded with lime plaster.

10. Construction Technology

Structural System Building Techniques	: Indo Persian : Arcuate : Priok and stone	
Material of Construction	: Brick and stone	

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Peeling of plaster.

12. Threats to the Property

✓ Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs		
	(Attach list as in page 6, in case of multiple photographs)	
Photo Reference		
CAPTION		
15. Audio / Video		
	(Related to rituals / performance / festivals etc.)	
Reference		
DESCRIPTION		
16. Maps/Plans/Drawings		
17. Listers		
NAME	NAME	
18. Reviewers		
NAME	NAME	
COMMENTS	COMMENTS	