



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SMP-007

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Shree Laxmi Narayan Mandir  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 73° 10' E

LATITUDE 27° 17' N

#### Address

Ward no 19, near Sorti Bazaar, Sawai Madhopur city

: **Village (village code)**

**Post** :Sawai Madhopur

**District**: Sawai Madhopur

**State** : Rajasthan

**PIN**: 322021

#### Approach

: The Temple is situated at Sawai Madhopur city. It is 7 KM away from Sawai Madhopur Railway station. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
  - Gateway
  - Pillar
  - Others (specify)
- Mandir**

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** The structure is a Nagar style temple and belongs to Lord Laxmi Narayan. The temple is made on an elevated platform with staircases. The superstructure is in curvilinear shape. The foliated arches are supported by broad columns. The structure has a big open courtyard in the vicinity of the temple and has multiple chhatris oblong as well as canopied.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 18<sup>th</sup> Century AD  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of :  
India / State Archaeology : State Government  
Department / Any Other (Please :  
specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** : Temple
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

<input type="checkbox"/>	Architectural	
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	The ceilings of the temple has a big medallion.

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Rural  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Storys : 02
  
- **Spatial Organization**  
Orientation : The temple is oriented East West and faces West.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Oblong and canopied chhatris, curvilinear superstructure  
  
Interiors : Big medallion on the ceiling.  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Nagar style of temple
- Building Techniques** : Arcuate and trabeate
- Material of Construction** : Brick Plaster

### 11. Condition Assessment

---

In General	Good / Fair
	Good

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

Excess soot deposition on the surface and conservation work is going on.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input checked="" type="checkbox"/> | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

**SECTION III: REFERENCES**

**13. Reference Sources** (published and unpublished textual details)

---

**14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

**15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

**16. Maps/Plans/Drawings**

---

**17. Listers**

---

**NAME**

**NAME**

**18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**