



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SMP-278

SECTION I : IDENTIFICATION

1. Name

Present : Zanana Kund
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 77°23' E

LATITUDE 26° 12' N

Address

Panch Kund, Bhagwat garh, Sawai Madhopur

: **Village (village code)**

Post : Bhagwat garh

District: Sawai Madhopur

State : Rajasthan

PIN: 322702

Approach

: The tank is situated at Panch Kund, Bhagwat Garh. It is 27 KM away from Sawai Madhopur railway station. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note. The water tank has been encased with stone slabs around it. It has steps leading to the kund (or tank). The side wall has niches.

4. Property Use

ABANDONED / IN USE : In use

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 18th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- | | | |
|------------------------------|--|---|
| Context | | * Drawings (Attach extra sheet if necessary) |
| Urban / Rural Setting | | Urban |
| Surroundings | | Stand in Isolation
Integral part of a Landscape / Street / Complex |

- | | | |
|-------------------------------|--|-----------------------|
| Quantification | | |
| Area Dimension (L x B x H) : | | (m / cm/ feet / inch) |
| Number of Blocks : | | |
| Number of Storys : | | |

- | | | |
|-----------------------------|---|--|
| Spatial Organization | | |
| Orientation : | The tank is oriented North - South and faces North. | |
| Plan : | | |
| Allocation of Spaces : | | |

ARCHITECTURAL STYLE

- | | |
|------------------------------|--|
| Ornamentation | |
| Exteriors : | |
| Interiors : | |
| Movable Collections : | |
| Any Other (specify) : | |

10. Construction Technology

- | | |
|-----------------------------------|---|
| Structural System : | |
| Building Techniques : | |
| Material of Construction : | Sandstone & plaster encasement around tank. |

11. Condition Assessment

In General	Good / Fair
	Good

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS