

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SMP-375

| | SECTION I : IDENTIFICATION |
|---|---|
| 1. Name | |
| Present Past Other Name (if any): | : Asharam : : |
| 2. Location | |
| LONGITUDE 77 ⁰ 23 [°] E | LATITUDE 26 ⁰ 12' N |
| Address | Sawai Madhopur Road, Baunli Sawai Madhopur |
| | : Village (village code) Post : Baunli District: Sawai Madhopur State : Rajasthan PIN: 322023 |
| Approach | : The Chhatri is situated at Baunli in Sawai Madhopur District. It is 40 km away from Sawai Madhopur. It is well connected by regular bus services. |

3. Property Type

| Buildings | Religious structures | Other Structures |
|------------------------------|--|---|
| Palace | Temple | Wall |
| Fort | Mosque | Gateway |
| Citadel | Minar | Pillar |
| Govt. building | Church | ✓ Others (specify) |
| Railway station | Monastery | Asharam |
| Defence building | Stupa | |
| Industrial building | Tomb, Mausoleum | |
| Other public buildings | | |
| Residential building | | |
| | | |
| Engineering structure | Open space and related structures | Note: The structure is made on a very highly elevated platform |
| Engineering structure Bridge | | |
| | structures | very highly elevated platform |
| Bridge | structures Public square | very highly elevated platform made of rocks and brick. The structure is a square shaped building with one door. It is broken |
| Bridge Tunnel | structures Public square Park or garden | very highly elevated platform made of rocks and brick. The structure is a square shaped |
| Bridge Tunnel | structures Public square Park or garden Graveyard | very highly elevated platform made of rocks and brick. The structure is a square shaped building with one door. It is broken |
| Bridge Tunnel | structures Public square Park or garden Graveyard Baolis, Well | very highly elevated platform made of rocks and brick. The structure is a square shaped building with one door. It is broken |

4. Property Use

| | ABANDONED / IN USE : Abandoned |
|------------------------------------|--|
| Present | : |
| Past | : |
| 5. Age (Source) | |
| PERIOD | : 18 th Century AD |
| YEARS | : |
| Precise date of Construction | : |
| Completion | : |
| Subsequent changes | : |
| Destruction / Demolition | : |
| 6. Ownership / Level of Protection | on |
| | SINGLE /MULTIPLE : |
| Public : Archaeological Survey of | : |
| India / State Archaeology | |
| Department / Any Other (Please | |
| specify) | |
| Private | : |
| Any other (Please specify) | : |
| Name | : |
| Address | : |
| Phone | : |
| 7. Association | |
| WITH EVENTS | |
| In History | : Asharam |
| In Rituals | : |
| In Building Construction | : |
| Any other (specify) | : |
| WITH PERSONS | |
| Patron | : |
| Architect / Engineer | : |
| Any other (specify) | : |
| 8. Statement of Significance | |
| ✓ Architectural | The asharam is made on a highly elevated structure made up o |
| Archaeological | rocks and bricks. |
| Historical | |
| Religious | |
| Any other (specify) | |

SECTION II: DESCRIPTION

| 9. | 9. Physical Description and Decorative Features | | |
|----|--|---|---|
| • | Context Urban / Rural Setting Surroundings | | * Drawings (Attach extra sheet if necessary) Rural Setting Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex |
| • | Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys | : | (m / cm/ feet / inch) 01 01 |
| • | Spatial Organization Orientation Plan Allocation of Spaces | : | The Asharam is oriented east/ west and faces the east. |
| • | CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify) | | Square shaped building |

10. Construction Technology

| Structural System | : | Flat Roof |
|--------------------------|---|----------------|
| Building Techniques | : | Trabeate |
| Material of Construction | : | Bricks & Stone |

11. Condition Assessment

In General

Good / Fair

Fair

✓ Sign of Deterioration
 ✓ Serious Deterioration
 Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Badly damaged, needs immediate conservation.

12. Threats to the Property

| \checkmark | Natural |
|--------------|-----------------|
| < | Negligence |
| | Vandalism |
| | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs | |
|-------------------------|---|
| | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference | |
| CAPTION | |
| 15. Audio / Video | |
| | (related to rituals / performance / festivals etc.) |
| Reference | |
| DESCRIPTION | |
| 16. Maps/Plans/Drawings | |
| | |
| | |
| 17. Listers | |
| NAME | NAME |
| 18. Reviewers | |
| NAME | NAME |
| COMMENTS | COMMENTS |