



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/UDP-038

SECTION I : IDENTIFICATION

1. Name

Present : Gulab Bag get 2
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 75° 33' E

LATITUDE 27°42' N

Address

Gulab Bag, Dath Talell Road Udaipur

: Village (village code)

Post: Udaipur

District: Udaipur

State: Rajasthan

PIN: 31001

Approach

: The Gateway is situated near Gulab Bag in Udaipur. It is 1km away from city bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is an iron gate at the entrance of a garden. Ornamented iron-grills are attached to it. The gate is in the state of deterioration.

4. Property Use

ABANDONED / IN USE :

Present : Gateway
Past : Gateway

5. Age (Source)

PERIOD : 20th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | | |
|--------------------------|---------------------|---|
| <input type="checkbox"/> | Architectural | |
| <input type="checkbox"/> | Archaeological | |
| <input type="checkbox"/> | Historical | |
| <input type="checkbox"/> | Religious | |
| <input type="checkbox"/> | Any other (specify) | : |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** * Drawings (Attach extra sheet if necessary)
Urban / Rural Setting
Surroundings
Stand in Isolation
Integral part of a Landscape / Street / Complex

 - **Quantification**
Area Dimension (L x B x H) :
(m / cm/ feet / inch)
Number of Blocks : 1
Number of Storys : 1

 - **Spatial Organization**
Orientation : This Gate is situated in Gulab Bag the oriented East/West and faces west.
Plan :
Allocation of Spaces :
- ARCHITECTURAL STYLE**
- **Ornamentation**
Exteriors : Ornamented iron grills are attached to the gate.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** :
- Building Techniques** :
- Material of Construction** :

11. Condition Assessment

In General **Good / Fair** **Good**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

Note – Plaster is peeling off.

In Brief (Attach extra sheet if necessary):

Rusting of iron.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Not available

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS