



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/UDP-058

SECTION I : IDENTIFICATION

1. Name

Present : Char Bhuja Jee Temple
Past :
Other Name (if any): :

2. Location

LONGITUDE 75° 33' E

LATITUDE 27°42' N

Address

Maji ki Bawari Jagdish Temple road Udaipur

: **Village (village code)**

Post: Udaipur

District: Udaipur

State: Rajasthan

PIN: 313001

Approach

: The Temple is situated on the Maji Ki Bawari Jagdish Mandir road. Its 1 ½km from bus stand Udaipur. It's well connected by regular bus stand.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: It is an old temple. It can be approached by means of a staircase. Several commercial shops near the temple. This is a wooden gate at the entrance which is painted with yellow colour. Circular metal knobs are attached to the door. The door lintels are lavishly ornamented

with intricate carving. There are minutely carved doorframes,

4. Property Use

ABANDONED / IN USE :

√

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 19thCentury AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	Door lintels are intricately carved.
<input type="checkbox"/>	Archaeological	

- Historical
- Religious
- Any other (specify) :

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- | | | |
|------------------------------|--|---|
| Context | | * Drawings (Attach extra sheet if necessary) |
| Urban / Rural Setting | | Urban |
| Surroundings | | Stand in Isolation
Integral part of a Landscape / Street / Complex |

- | | | |
|-------------------------------|----|-----------------------|
| Quantification | | |
| Area Dimension (L x B x H) : | | (m / cm/ feet / inch) |
| Number of Blocks : | 01 | |
| Number of Storys : | 01 | |

- | | | |
|-----------------------------|---|--|
| Spatial Organization | | |
| Orientation : | The Temple oriented in East/West and facing West. | |
| Plan : | | |
| Allocation of Spaces : | | |

ARCHITECTURAL STYLE

- | | | |
|------------------------------|---|--|
| Ornamentation | | |
| Exteriors : | Carved pillars and ornamented doorframes. | |
| Interiors : | Stone image of deity having four hands. | |
| Movable Collections : | | |
| Any Other (specify) : | | |

10. Construction Technology

- | | | |
|---------------------------------|--|-------------------|
| Structural System | | Indo-Parisian |
| Building Techniques | | Nagara |
| Material of Construction | | Stone and bricks. |

11. Condition Assessment

In General	Good / Fair	Good
-------------------	--------------------	-------------

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

Note – Plaster is peeling off.

In Brief (Attach extra sheet if necessary):

Discoloration.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS