



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-067

SECTION I : IDENTIFICATION

1. Name

Present : Satta pole
Past :
Other Name (if any): :

2. Location

LONGITUDE 75° 33' E

LATITUDE 27°42' N

Address

Gadiya Devara, Udaipur.

: **Village (village code)**

Post : Udaipur

District: Udaipur

State: Rajasthan

PIN: 313001

Approach

: The Satta pole is situated in gadiya devara. It is 1½km away from bus stand Udaipur. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Raiay station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|-------------------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input checked="" type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: It is a painted gateway. It has foliated arch opening which has medallion on either side of the spandrel. The gateway has multi-angular bastions on either side. A battle mented parapet wall is on the gateway has metal knobs fitted in it. The vault of the arch is supported by start brackets.

4. Property Use

ABANDONED / IN USE[√]

Present : Gateway
Past : Gateway

5. Age (Source)

PERIOD : 17th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	Arched gateway.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban√ / Rural Setting
Surroundings
*** Drawings (Attach extra sheet if necessary)**
Urban setting
Stand in Isolation
Integral part of a Landscape / Street / Complex

 - **Quantification**
Area Dimension (L x B x H) :
(m / cm/ feet / inch)
Number of Blocks : 01
Number of Storys : 01

 - **Spatial Organization**
Orientation : The Satta pole is situated East/West and faces the East.
Plan :
Allocation of Spaces :
- ARCHITECTURAL STYLE**
- **Ornamentation**
Exteriors : Multi-angular leasions on either side of the gateway.
Interiors :
Movable Collections :
- Any Other (specify) :**

10. Construction Technology

- Structural System** : Indo –Persian
- Building Techniques** : Trabeate system
- Material of Construction** : Stone and brick.

11. Condition Assessment

In General

Good / Fair Good

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Discoloration, black patches, exposed tanks etc.

12. Threats to the Property

<input checked="" type="checkbox"/>	Natural
<input type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Not available

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS