

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-076 **SECTION I: IDENTIFICATION** 1. Name Present Banke Bihari Ji Ka Mandir. **Past** Other Name (if any): 2. Location LONGITUDE **LATITUDE** Address Jagdish Chowk , Gangaaur Ghat, Udaipur. Village (village code) Post: Udaipur **District:** Udaipur State: Rajasthan **PIN:** 313001 Approach The Temple is situated in Udaipur. It is 2km away from bus stand Udaipur. It is well connected by regular bus services. 3. Property Type Religious structures Other Structures **Buildings** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify): Haveli Raiay station Monastery Defence building Stupa Industrial building Tomb. Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a temple of tri-ratha plan. The temple is adorned with structures Bridge Public square bas relief of elephant and horses. Park or garden It is adorned with perforated Tunnel windows. The interior of the Other engineering structure Graveyard temple has sculptors of the "Baja Baolis, Well Samghat" and "Haya Samghat". Tank The temple can be approached by Cave

means of lofity staircases. It has

4. Property Use	
	ABANDONED/INUSE:In use
Present Past	: Religious : Religious
5. Age (Source)	
PERIOD YEARS	: 19 th Century AD :
Precise date of Construction Completion Subsequent changes	: : :
Destruction / Demolition	•
6. Ownership / Level of Protection	ion
	SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:
Private Any other (Please specify) Name Address Phone	Dev Sthan Vibhag, Rajasthan:::
7. Association	•
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance	: : : :
✓ ArchitecturalArchaeologicalHistoricalReligious	Perforated windows and scole bas relief.

Any other (specify)	:	
SECTION II: DESCRIPTION		
9. Physical Description and Decorative Features		
 Context Urban√ / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) Urban setting	
oun oun unigo	Stand in Isolation Integral part of a Landscape / Street / Complex	
Quantification Area Dimension (L x B x H)	: (m / cm/ feet / inch)	
Number of Blocks Number of Storys	: 01 : 01	
 Spatial Organization Orientation 	: The Mandir is oriented in North/South and faces the North.	
Plan Allocation of Spaces	: :	
ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Moyable Collections	 It has a number of graduated projections. It has a curvilinear shikhar. A beautiful image of the deity in traditional attire. 	
Any Other (specify)	:	
10. Construction Technology		
Structural System	: Negara style of temple.	
Building Techniques Material of Construction	: Trabeate system: Stone.	
11. Condition Assessment		
In General Good / Fair: Good		
233.4	Sign of Deterioration Serious Deterioration	

	Danger of Disappearance		
In Brief (Attach extra sheet if necessary): Discoloration presence of dirty and dust, peeling of plaster etc.			
12. Threats to the Property			
√	Natural Negligence Vandalism Urban Pressures		

SECTION III: REFERENCES

13. Reference Sources (published ar	nd unpublished textual details)
Not available	
14. Photographs	
14. I notographs	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
Thoto Reference	
CAPTION	
4F Audio / Wideo	
15. Audio / Video	(Related to rituals / performance / festivals etc.)
Deference	(Notated to Madio / portormando / roduvalo oto.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
17. Listers	
NAME	NAME
40 D	
18. Reviewers	
NAME	NAME
0011151150	0011171170
COMMENTS	COMMENTS