

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/UDP-078 **SECTION I: IDENTIFICATION** 1. Name Present Shiv Jee Mandir Past Other Name (if any): 2. Location LONGITUDE **LATITUDE Address** Gangaur Ghat, Udaipur. Village (village code) Post: Udaipur **District:** Udaipur State: Rajasthan **PIN:** 313001 The Mandir is situated at Gungaur Ghat on the bank of **Approach** pichhola lake. It is 2km away from bus stand Udaipur. It is well connected by regular bus services. 3. Property Type Religious structures **Buildings** Other Structures Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is an old temple structures dedicated to lord shiva. The temple has spire surmounted by Bridge Public square an amalaka. The door of the deity Park or garden Tunnel room has iron grills which are Other engineering structure Graveyard painted with green color. Framed Baolis, Well photos are hanging on the walls. Tank There is a stone image of Nandi Cave facing towards main deity. A number of residential buildings are

near the temple.

| 4. Property Use | | | | |
|--|---------------------------------|--|--|--|
| | ABANDONED / IN USE : | | | |
| | $\sqrt{}$ | | | |
| Present | : Religious. | | | |
| Past | : Religious. | | | |
| 5. Age (Source) | | | | |
| 3. Age (Source) | | | | |
| PERIOD | : 18th Century AD. | | | |
| YEARS | : | | | |
| Precise date of Construction | : | | | |
| Completion | | | | |
| Subsequent changes | : | | | |
| Destruction / Demolition | : | | | |
| 6. Ownership / Level of Protecti | ion | | | |
| • | SINGLE /MULTIPLE : | | | |
| Public: Archaeological Survey of | : | | | |
| India / State Archaeology | | | | |
| Department / Any Other (Please | | | | |
| specify) | | | | |
| Private | : : | | | |
| Any other (Please specify) Name | : • | | | |
| Address | | | | |
| Phone | · : | | | |
| | | | | |
| 7. Association | | | | |
| WITH EVENTS | | | | |
| In History | : | | | |
| In Rituals | : | | | |
| In Building Construction Any other (specify) | : • | | | |
| WITH PERSONS | • | | | |
| Patron | | | | |
| Architect / Engineer | | | | |
| Any other (specify) | : | | | |
| 2 | | | | |
| 8. Statement of Significance | | | | |
| √ Architectural | Inverted lotus type of pinnate. | | | |
| Archaeological | | | | |
| Historical Religious | | | | |
| Any other (specify) | : | | | |

SECTION II: DESCRIPTION

| 9. | Physical Description and De | cora | ative Features | | |
|-----------|--|-------|---|--|--|
| • | Context Urban / Rural Setting Surroundings | | * Drawings (Attach extra sheet if necessary) | | |
| | J | | Stand in Isolation Integral part of a Landscape / Street / Complex | | |
| • | Quantification Area Dimension (LxBxH) | : | (m / cm/ feet / inch) | | |
| | Number of Blocks Number of Storys | : | 01 01 | | |
| • | Spatial Organization Orientation Plan Allocation of Spaces | : : : | The Mandir is oriented East/ West and faces the West. | | |
| <u>AR</u> | CHITECTURAL STYLE Ornamentation Exteriors | : | The temple has a dome surmounted by an inverted lotus type of pinnacle. | | |
| An | Interiors Movable Collections y Other (specify) | : : | A stone image of Mandir. | | |
| 10. | Construction Technology | | | | |
| | Structural System Building Techniques Material of Construction | : : : | Nagara style of temple. Trabeate system. Brick and stone. | | |
| 11. | Condition Assessment | | | | |
| | In General Go | ood | / Fair Good | | |
| | | | Sign of Deterioration Serious Deterioration Danger of Disappearance | | |
| No | te – Plaster is peeling off. | | | | |
| ln | In Brief (Attach extra sheet if necessary): | | | | |

| Peeling of plaster, discoloration, dismantled parts etc. | | | | |
|--|-----------------|--|--|--|
| | | | | |
| 12. Threats to the Property | | | | |
| | Natural | | | |
| | √ Negligence | | | |
| | Vandalism | | | |
| | Urban Pressures | | | |
| | | | | |

SECTION III: REFERENCES

| 13. Reference Sources (published and | unpublished textual details) |
|--------------------------------------|---|
| Not available | |
| | |
| | |
| | |
| 14. Photographs | |
| | (Attach list as in page 6, in case of multiple photographs) |
| Photo Reference | |
| CAPTION | |
| CAPTION | |
| 15. Audio / Video | |
| | (Related to rituals / performance / festivals etc.) |
| Reference | |
| DESCRIPTION | |
| | |
| 16. Maps/Plans/Drawings | |
| | |
| | |
| 17. Listers | |
| Tr. Listers | |
| NAME | NAME |
| 18. Reviewers | |
| | NAME. |
| NAME | NAME |
| COMMENTS | COMMENTS |
| | |