


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-088

	SECTION I : IDENTIFICATION	
1. Name		
Present	: Bairaj Kund	
Past Other Name (if any):	:	
2. Location		
LONGITUDE 75°31'E	LATITUDE 27°42'N	
Address	: Delhi Gate ,Udaipur	
	: Village (village code)	
	Post: Udaipur State: Rajasthan	District: Udaipur PIN: 313001
Approach district	3km away from c	ear Delhi Gate in Udaipur. It is ity bus stand udaipur. It is well jular bus services.

3. Property Type



4. Property Use

		ABANDONED√ / IN USE	
Present Past 5. Age (Source)	:	Secred pond	
PERIOD YEARS	:	18 th Century AD	
Precise date of Construction Completion Subsequent changes Destruction / Demolition	:		
6. Ownership / Level of Protection			
		SINGLE /MULTIPLE :	
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private	:		
Any other (Please specify)	:		
Name	:		
Address	:		
Phone	:		
7. Association			
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 			
8. Statement of Significance			
Architectural			

Archaeological Historical Religious Any other (specify)

:

9. Physical Description and Decorative Features * Drawings (Attach extra sheet if necessary) Context Urban $\sqrt{}$ Rural Setting Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex Quantification Area Dimension (L x B x H) : (m / cm/ feet / inch) Number of Blocks : Number of Storys : • Spatial Organization Orientation : The Kund is oriented East/West and faces the West Plan Allocation of Spaces : **ARCHITECTURAL STYLE** Ornamentation Exteriors : The 'Haven Kund' has number of chhatri with dome and chhajjas. Interiors : **Movable Collections** : Any Other (specify) :

SECTION II: DESCRIPTION

10. Construction Technology

Structural System	:
Building Techniques	:
Material of Construction	:

11. Condition Assessment

In General

Good / Fair√ Fair

 $\sqrt{}$ Sign of Deterioration

Serious Deterioration
Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Not being maintained properly

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	(Attach list as in page 0, in case of multiple photographs)
CAPTION	
15. Audio / Video	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS