



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-092

SECTION I : IDENTIFICATION

1. Name

Present : Shree Chaumukh Maharaj Mandir

Past :

Other Name (if any): :

2. Location

LONGITUDE 75°31'E

LATITUDE 27°42'N

Address : Bara Bazaar, Udaipur

: **Village (village code)**

Post: Udaipur

District: Udaipur

State: Rajasthan

PIN: 313001

Approach district : The Temple is situated at Bara Bazaar in Udaipur; it is 2km away from bus stand Udaipur. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: it is a Temple which can be approached through a painted gateway. Marble image of deity is placed on a raised platform.

4. Property Use

ABANDONED/ IN USE :√

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 18thCentury AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	
<input type="checkbox"/>	Archaeological	: An oblong chattri on top of the entrance.
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** * Drawings (Attach extra sheet if necessary)
Urban **Rural Setting**
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks : 01
Number of Storys : 01

- **Spatial Organization**
Orientation : The Temple is oriented East/ West and faces the West.

Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Oblong chattri is clad with lime plaster,
Interiors : Gland Marble statue of Deity.
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo-Persian
Building Techniques : Trabeate system
Material of Construction : Stone, Plaster and marble.

11. Condition Assessment

In General **Good / Fair** **Fair**

- | | |
|---|-------------------------|
| √ | Sign of Deterioration |
| | Serious Deterioration |
| | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Peeling of plaster, Discoloration, Damaged Chhajjas etc,

12. Threats to the Property

<input checked="" type="checkbox"/>	Natural
<input type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS