

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-096

1. Name	SECTION I : IDENTIFICATION
Present	: Chille Masjid Ka well
Past Other Name (if any):	:
2. Location	
LONGITUDE 75°31'E	LATITUDE 27°42'N
Address	: Bard Bazzar, Udaipur
	: Village (village code)
	Post: UdaipurDistrict: UdaipurState: RajasthanPIN: 313001
Approach district	: The well is situated at Bara Bazar in Udaipur. It is 3km away from bus stand .it is well connected by regular bus services
3. Property Type	
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structuresOther StructuresTempleWallMosqueGatewayMinarPillarChurchOthers (specify)MonasteryStupaTomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Note: it is a rectangular well cladded with rubble masonry and lime-plaster. An iron-pipe is attached to the well for fetching water. ✓ Baolis, Well ✓ Tank ✓ Cave

4. Property Use

		ABANDONED/IN USE: $$
Present Past	:	Religious Drinking water
5. Age (Source)		
PERIOD YEARS	:	17 th Century AD
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : :	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address	:	
Phone	:	
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	:	
8. Statement of Significance		
 ✓ Architectural Archaeological Historical Religious Any other (specify) 	Re :	ctangular well cladode with rubble masonry.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

 Context Urban √/ Rural Setting Surroundings 			* Drawings (Attach extra sheet if necessary) Urban setting	
			Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:	(m/om/fact/inch)	
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01	
•	Spatial Organization Orientation	:	The Well is oriented East/West and faces the East.	
	Plan Allocation of Spaces	:		
<u>AF</u> •	RCHITECTURAL STYLE Ornamentation			
Ar	Exteriors Interiors Movable Collections by Other (specify)	:	The well is cladded with rubble masonry and plaster.	

10. Construction Technology

Structural System	:	Rectangular well
Building Techniques	:	Stone –cladding
Material of Construction	:	Rubble masonry and plaster.

11. Condition Assessment

In General

Good / Fair√ Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Peeling of plaster.

12. Threats to the Property

 Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	(Attach list as in page 0, in case of multiple photographs)
CAPTION	
15. Audio / Video	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS