

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological and Heritage Sites / Monuments

#### Serial No.: RJ/UDP-125

| 1. Name   | SECTION I: IDENTIFICATIO   | DN  |
|---|--|---|
| Present<br>Past<br>Other Name (if any):   | : Samadhi<br>:   |   |
| 2. Location   |  |   |
| LONGITUDE 75°31'E   | LATITUDE 27°42'N   |   |
| Address   | Near Baghela Talab, Nag  | gda Nagari  |
|   | : Village (village code  | ))  |
|   | <b>Post:</b> Kailashpuri<br><b>State:</b> Rajasthan  | District: Udaipur<br>PIN: 313202  |
| Approach  |  | ated at Nagda Naguri in Udaipur<br>way from bus stand Udaipur. It is<br>gular bus services.   |
| 3. Property Type  |  |   |
| Buildings     Palace     Fort     Citadel     Govt. building     Railway station     Defence building     Industrial building     Other public buildings     Residential building | Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum   | Other Structures     Wall     Gateway     Pillar     ✓     Others (specify)     Cenotaph  |
| Engineering structure     Bridge     Tunnel     Other engineering structure   | Open space and related<br>structuresPublic square<br>Park or garden<br>Graveyard<br>Baolis, Well<br>Tank<br>Cave | <b>Note:</b> It is a raised platform with<br>Shivlinga at the centre. The<br>structure is in a ruined state. The<br>platform is made of bricks and<br>plaster. It is badly dilapidated due<br>to vegetational growth. |

| 4. Property Use                    |                                |
|------------------------------------|--------------------------------|
| The roperty use                    | ABANDONED / IN USE:√           |
|                                    |                                |
| Present                            | ·                              |
| Past                               |                                |
|                                    | •                              |
| 5. Age (Source)                    |                                |
|                                    |                                |
| PERIOD                             | : 17 <sup>th</sup> Century AD. |
| YEARS                              |                                |
|                                    |                                |
| Precise date of Construction       | :                              |
| Completion                         | :                              |
| Subsequent changes                 | :                              |
| Destruction / Demolition           | :                              |
|                                    |                                |
| 6. Ownership / Level of Protection | on                             |
|                                    | SINGLE /MULTIPLE :             |
| Dublic Archeological Ourses of     |                                |
| Public : Archaeological Survey of  |                                |
| India / State Archaeology          |                                |
| Department / Any Other (Please     |                                |
| specify)                           |                                |
| Private                            |                                |
| Any other (Please specify)         |                                |
| Name                               |                                |
| Address                            |                                |
| Phone                              |                                |
| 7. Association                     |                                |
|                                    |                                |
| WITH EVENTS                        |                                |
| In History                         | :                              |
| In Rituals                         | :                              |
| In Building Construction           | :                              |
| Any other (specify)                | :                              |
| WITH PERSONS                       |                                |
| Patron                             | :                              |
| Architect / Engineer               | :                              |
| Any other (specify)                |                                |
|                                    |                                |
| 8. Statement of Significance       |                                |
| ✓ Architectural                    | Hypaetheral structure          |
| Archaeological                     |                                |
| Historical                         |                                |
| Deligious                          |                                |

Religious√√Any other (specify)::Cenotaph

# SECTION II: DESCRIPTION

# 9. Physical Description and Decorative Features

| Context Urban / Rural Setting Surroundings |   |   | * <b>Drawings (</b> Attach extra sheet if necessary)<br>Urban         |  |
|--|---|---|---|--|
|  | ourroundings  |   | Stand in Isolation<br>Integral part of a Landscape / Street / Complex |  |
| •  | <b>Quantification</b><br>Area Dimension ( L x B x H)  | : | (m/m)   |  |
|  | Number of Blocks<br>Number of Storys  | : | (m / cm/ feet / inch)   |  |
| •  | Spatial Organization<br>Orientation   | : | The Samadhi is oriented North/South and face the South.               |  |
|  | Plan<br>Allocation of Spaces  | : |   |  |
| •  | <b>RCHITECTURAL STYLE</b><br>Ornamentation<br>Exteriors<br>Interiors<br>Movable Collections<br>by Other (specify) |   | Marbles statue of Nandi facing towards Shivlingam.                    |  |
|  |   | • |   |  |

#### **10. Construction Technology**

| Structural System<br>Building Techniques | : | Raised platform<br>Stone masonry |
|--|---|----------------------------------|
| Material of Construction                 | : | Stone and plaster.               |

#### 11. Condition Assessment

In General

Good / Fair Good

| Si |
|----|
| S  |
| D  |

Sign of Deterioration Serious Deterioration Danger of Disappearance

#### In Brief (Attach extra sheet if necessary):

Cracks, discoloration, loss of cementing material and vegetational growth.

#### 12. Threats to the Property

|  | Natural         |
|--|-----------------|
|  | Negligence      |
|  | Vandalism       |
|  | Urban Pressures |

## **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs         | (Attach list as in page 6, in case of multiple photographs) |
|-------------------------|---|
| Photo Reference         | (Attach list as in page 0, in case of multiple photographs) |
| CAPTION                 |   |
| 15. Audio / Video       | (Related to rituals / performance / festivals etc.)         |
| Reference               |   |
| DESCRIPTION             |   |
| 16. Maps/Plans/Drawings |   |
|                         |   |
| 17. Listers             |   |
| NAME                    | NAME  |
| 18. Reviewers           |   |
| NAME                    | NAME  |
| COMMENTS                | COMMENTS  |