

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/UDP-148

1. Name	SECTION I: IDENTIFICATIO	DN
Present Past Other Name (if any):	: Bhawani Kund :	
2. Location		
LONGITUDE 75°31'E	LATITUDE 27°42'N	
Address	Digambar Jain Mandir, S	alumbar
	: Village (village code	2)
	Post: Salumbar State: Rajasthan	District: Udaipur PIN: 313027
Approach		at Salumbar in Udaipur District. It us stand Udaipur District. It is well bus services.
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, Well√TankCave	Note: This rectangular 'Kund' is cladded with lime-plaster. The 'Kund' was being used for religious purpose. It is no longer in use.

4. Property Use	
	ABANDONED √/ IN USE
	•
Present	
Past	
	•
5. Age (Source)	
PERIOD	: 17 th Century AD.
YEARS	· · · · · ·
Precise date of Construction	
Completion	
Subsequent changes	
Destruction / Demolition	
6. Ownership / Level of Protecti	on
6. Ownership / Level of Protection	
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	
India / State Archaeology	•
Department / Any Other (Please	
specify)	
Private	
Any other (Please specify)	
Name	
Address	
Phone	
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	
Architect / Engineer	
Any other (specify)	
Any other (specify)	
8. Statement of Significance	
Architectural	'Kund' cladded with rubble masonry.
Archaeological	Nuna diadaea with rubble masonry.
Historical	

- Religious Any other (specify)

:

9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Rural
	Carrounango		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m/om/fact/inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Tank is oriented North/South and face the South.
<u>A</u> F •	RCHITECTURAL STYLE Ornamentation Exteriors	:	Rectangular tank having a gate at the entrance filled with ornamented circular iron-ring.
Ar	Interiors Movable Collections y Other (specify)	: : :	

SECTION II: DESCRIPTION

10. Construction Technology

Structural System	:	Rectangular pond
Building Techniques	:	Stone cladding
Material of Construction	:	Stone.

11. Condition Assessment

In General

Good / Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Peeling of plater, fading of paint sand discoloration.

12. Threats to the Property

 Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	(Attach list as in page 0, in case of multiple photographs)
CAPTION	
15. Audio / Video	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS