



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/UDP-149

SECTION I: IDENTIFICATION

1. Name

Present : Krishna Pole
 Past :
 Other Name (if any):

2. Location

LONGITUDE 75°31'E

LATITUDE 27°42'N

Address

Gati Darwaja, ward no. 13

: **Village (village code)**

Post: Salumbar

District: Udaipur

State: Rajasthan

PIN: 313027

Approach

: The Gateway is situated at Salumbar in Udaipur District. It is 80km away from bus stand Udaipur District. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: This gateway is adorned with carved and painted stone-bracketed. The upper structure is missing. It has battlemented parapet and multi-angular bastions.

4. Property Use**ABANDONED / IN USE** ✓

Present : Gateway
Past : Gateway

5. Age (Source)

PERIOD : 16th Century AD.
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection**SINGLE / MULTIPLE :**

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	Multi-angular bastions.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban / Rural Setting
Surroundings
*** Drawings** (Attach extra sheet if necessary)
Rural Setting
Stand in Isolation
Integral part of a Landscape / Street / Complex
- **Quantification**
Area Dimension (L x B x H) :
(m / cm/ feet / inch)
Number of Blocks : 01
Number of Storys : 01
- **Spatial Organization**
Orientation : The Gateway is oriented East/West and face the West.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Pointed and carved stone brackets.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo-Persian
Building Techniques : Stone masonry
Material of Construction : Stone.

11. Condition Assessment

In General

Good / Fair

- | | |
|-------------------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input checked="" type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Discoloration, peeling of plaster, fading of paints and vegetation growth.

12. Threats to the Property

√	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Not available

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS