



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/UDP-150

SECTION I: IDENTIFICATION

1. Name

Present : Maa Jee Ka Bawari
 Past :
 Other Name (if any):

2. Location

LONGITUDE 75°31'E

LATITUDE 27°42'N

Address

Maa Jee Ka Bawari, Salumbar

: **Village (village code)**

Post: Salumbar

District: Udaipur

State: Rajasthan

PIN: 313027

Approach

: The Bawari is situated at Salumbar in Udaipur District. It is 80km away from bus stand Udaipur district. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: This rectangular step well is clad with rubble masonry and lime-plaster. It can be approached through descending staircases.

4. Property Use**ABANDONED / IN USE**

:

Present :**Past** :**5. Age (Source)**

PERIOD : 18thCentury AD.**YEARS** :**Precise date of Construction** :**Completion** :**Subsequent changes** :**Destruction / Demolition** :**6. Ownership / Level of Protection**

SINGLE /MULTIPLE :**Public** : Archaeological Survey of
India / State Archaeology
Department / Any Other (Please
specify)**Private** :**Any other (Please specify)** :**Name** :**Address** :**Phone** :**7. Association**

• **WITH EVENTS****In History** :**In Rituals** :**In Building Construction** :**Any other (specify)** :• **WITH PERSONS****Patron** :**Architect / Engineer** :**Any other (specify)** :**8. Statement of Significance**

<input checked="" type="checkbox"/>	Architectural	Cladded with rubble masonry.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban / Rural Setting
Surroundings
*** Drawings** (Attach extra sheet if necessary)
Rural Setting
Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) :
(m / cm/ feet / inch)
Number of Blocks :
Number of Storys :

- **Spatial Organization**
Orientation : The Bawari is oriented East/West and face the East.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Lime-plaster coating.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Rectangular step well.
- Building Techniques** : Stone cladding.
- Material of Construction** : Rubble masonry and plaster.

11. Condition Assessment

In General **Good / Fair** **Fair**

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Badly damaged

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS