

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

# Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/Udp-236

SECTION I : IDENTIFICATION 1. Name			
Present	: Chille Masjid Ka well		
Past Other Name (if any):	: :		
2. Location			
LONGITUDE 75°31'E	LATITUDE 27°42'N		
Address	: Bara Bazaar, Udaipur		
	: Village (village code)		
	Post: UdaipurDistrict: UdaipurState: RajasthanPIN: 313001		
Approach district	: This Well is situated In Bara Bazaar in Udaipur. It is 2km away from bus stand Udaipur. It is well connected by regular bus services.		
3. Property Type			
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structuresOther StructuresTempleWallMosqueGatewayMinarPillarChurch✓MonasteryStupaTomb, Mausoleum		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote: It is a rectangular well cladded with rubble masonry and lime-plaster. An iron-pipe is attached to the well for fetching water.Park or garden Graveyard Baolis, Well Tank CaveNote: It is a rectangular well 		

#### 4. Property Use ABANDONED / IN USE $\sqrt{}$ Present 2 Religious Past Drinking water : 5. Age (Source) 17<sup>th</sup> Century AD PERIOD : YEARS 2 Precise date of Construction 2 Completion 2 Subsequent changes 1 **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify)state Govt. Private 2 Any other (Please specify) : Name 2 Address 2 Phone 2 7. Association • WITH EVENTS In History 2 In Rituals 2 In Building Construction 2 Any other (specify) : WITH PERSONS Patron 2 Architect / Engineer 2 Any other (specify) 2 8. Statement of Significance

 Architectural	Rectangular well cladded with rubble masonry.
Archaeological	
Historical	
Religious	
Any other (specify)	:

9. Physical Description and Decorative Features			
•	Context Urban √/ Rural Setting Surroundings		* <b>Drawings (</b> Attach extra sheet if necessary) Urban setting
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	
•	<b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	The Well is oriented East/West and faces the East.
ARCHITECTURAL STYLE <ul> <li>Ornamentation</li> </ul>			
Ar	Exteriors Interiors Movable Collections <b>by Other</b> (specify)	:	The Well is cladded with rubble masonry and plaster.

# **SECTION II: DESCRIPTION**

### **10. Construction Technology**

Structural System	:	Rectangular well
<b>Building Techniques</b>	:	Stone –cladding
Material of Construction	:	Rubble masonry and plaster.

#### 11. Condition Assessment

In General

**Good / Fair** $\sqrt{}$  **Fair** 

	Si
	S
	D

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Peeling of plaster.

# 12. Threats to the Property



# **SECTION III:** REFERENCES

#### 13. Reference Sources (published and unpublished textual details)

Not available

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS