

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-253 **SECTION I: IDENTIFICATION** 1. Name Present Mandir **Past** Other Name (if any): 2. Location **LONGITUDE** 75°31'E LATITUDE 27°42'N **Address** Sas Bahu Mandir, Nagada. Village (village code) Nagada Post: Kailashpuri District: Udaipur State: Rajasthan PIN: 313202 Approach district The Temple is situated at Nagada in Udaipur District. It is 23km away from Udaipur bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Note: The temple is in a dilapidated condition. Pillars "Bhar are crowned with Wahak" gandharva. Delicate carving on the interior walls door-lintel is adorned with decorative designs. Engineering structure Open space and related structures Bridge Public square Park or garden Tunnel Other engineering structure Graveyard Baolis, Well

Tank
Cave

4. Property Use

		ABANDONED√/ IN USE
Present Past	:	Religious
5. Age (Source)		
PERIOD YEARS	:	15 th Century AD
Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protecti	: : :	
o. Ownership / Level of 1 Totecti	<u> </u>	SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology	:	

7. Association

Private

Name Address Phone

• WITH EVENTS

Department / Any Other (Please specify)state Govt.

Any other (Please specify)

In History :
In Rituals :
In Building Construction :
Any other (specify) :

• WITH PERSONS

Patron :

Any other (specify) 8. Statement of Significance Architectural Pillars are carved and adorned with "Bhar-Wahak" Gandharva. Archaeological Historical Religious Any other (specify) : **SECTION II: DESCRIPTION** 9. Physical Description and Decorative Features * **Drawings** (Attach extra sheet if necessary) Context Urban / Rural Setting √ Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex Quantification Area Dimension (LxBx: (m / cm/ feet / inch) H) 01 Number of Blocks Number of Storys 01 Spatial Organization Orientation The Temple is oriented East/West and faces the East. Plan Allocation of Spaces **ARCHITECTURAL STYLE** Ornamentation Exteriors Delicate carving on the walls. Door-lintel studded with decorative designs. Interiors **Movable Collections** Any Other (specify) 10. Construction Technology

Architect / Engineer

Structural System

Building Techniques

Material of Construction

Indo-Persian

Stone.

Tribute system

11. Condition Assessm	ent	
In General	Good / Fair	
	Sign of Deterioration √ Serious Deterioration Danger of Disappearance	
In Brief (Attach extra sheet if necessary): Blackening and vegetation growth. Cracks, discolouration, chipping of stones.		
12. Threats to the Prop	erty	
	√ NaturalNegligenceVandalismUrban Pressures	

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
IVAIVIL	IVAIVIE
COMMENTS	COMMENTS