

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-256 **SECTION I: IDENTIFICATION** 1. Name Present Mandir Past Other Name (if any): 2. Location **LONGITUDE** 75°31'E LATITUDE 27°42'N **Address** Sas Bahu Mandir, Nagada Village (village code) Nagada Post: Kailashpuri District: Udaipur State: Rajasthan PIN: 313202 Approach district The Temple is situated at Nagada in Udaipur district. It is 23km away from Udaipur bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Remain of a temple Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Note: It is a plinth level of a temple built on a raised platform having carved pattern. The upper portion has fallen off due to age. Engineering structure Open space and related structures Public square Bridge Park or garden Tunnel Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use

ABANDONED√/ IN USE

Present

Past : Religious

5. Age (Source)

PERIOD : 17th Century AD

YEARS

Precise date of Construction :

Completion : Subsequent changes :

Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

State Archaeology Department

Public: Archaeological Survey of :

India / State Archaeology

Department / Any Other (Please

specify)state Govt.

Private

Any other (Please specify) : Name :

Address :

Phone

7. Association

• WITH EVENTS

In History

In Rituals
In Building Construction

Any other (specify)

WITH PERSONS

Patron :
Architect / Engineer :
Any other (appoint)

8. Statement of Significance					
√ 	Architectural Archaeological Historical Religious Any other (specify)	F :	Raised platform of stone.		
	<u> </u>	SEC	CTION II: DESCRIPTION		
9.	Physical Description and De	cor	ative Features		
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)		
	Cancanange		Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)	:	(m / om/foot / inch)		
	Number of Blocks Number of Storys	: 01 : 01			
•	Spatial Organization Orientation Plan Allocation of Spaces	: : : : : : : : : : : : : : : : : : : :	The Temple is situated East/West and faces the East.		
<u>AF</u>	RCHITECTURAL STYLE Ornamentation Exteriors		Carved pattern.		

Interiors

Movable Collections Any Other (specify)

10. Construction Technology

Structural System Building Techniques Material of Construction Raised platform of stone. Stone masonry Stone and plaster.

11. Condition Assessme	ent			
In General	Good / Fair			
	Sign of Deterioration √ Serious Deterioration Danger of Disappearance			
In Brief (Attach extra sheet if necessary): blackening and vegetation growth. Badly damaged.				
12. Threats to the Prope	rty			
	√ NaturalNegligenceVandalismUrban Pressures			

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS