

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-259 **SECTION I: IDENTIFICATION** 1. Name Present Mandir Past Other Name (if any): 2. Location **LONGITUDE** 75°31'E LATITUDE 27°42'N **Address** Sas Bahu Mandir, Nagada. Village (village code) Post: kailashpuri **District**: Udaipur State: Rajasthan PIN: 313202 Approach district The Temple is situated at Nagada in Udaipur District. It is 23km away from Udaipur bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Note: This is an old temple having mutilated 'Amalaka'. The temple has multiple turrets and 'Bhumi Amalakas'. Pillars are studded 'Bharwahak Gandharva'. Engineering structure Open space and related structures Public square Bridge Park or garden Tunnel Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use

ABANDONED/ IN USE√

Present : Tourist site
Past : Religious

5. Age (Source)

PERIOD : 15th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public: Archaeological Survey of : ASI

rubile . Alchaeological Survey of .

India / State Archaeology

Department / Any Other (Please

specify)state Govt.

Private

Any other (Please specify)
Name

Address

Phone

7. Association

• WITH EVENTS

In History In Rituals

In Building Construction:

Any other (specify) :

• WITH PERSONS

Patron : Architect / Engineer :

Any other (specify)	:
8. Statement of Significance	
 ✓ Architectural ✓ Archaeological Historical Religious Any other (specify) 	Shikhara has multiple projections with recess.
	SECTION II: DESCRIPTION
9. Physical Description and De	corative Features
 Context Urban / Rural Setting √ Surroundings 	* Drawings (Attach extra sheet if necessary)
Guil Guillainige	Stand in Isolation Integral part of a Landscape / Street / Complex
Quantification Area Dimension (L x B x H)	: (m / cm/ feet / inch)
Number of Blocks Number of Storys	: 01 : 01
 Spatial Organization Orientation Plan Allocation of Spaces 	: The Temple is situated East/West and faces the East. :
ARCHITECTURAL STYLEOrnamentation Exteriors	: Curvilinear shikhar having mutilated 'Amalaka' and no pinnacle
Interiors Movable Collections Any Other (specify)	
10. Construction Technology	
Structural System Building Techniques Material of Construction	Nagara style of templeTrabeate systemStone.

11. Condition Assessme	ent	
In General	Good √/ Fair	
	✓ Sign of DeteriorationSerious DeteriorationDanger of Disappearance	
In Brief (Attach extra sheet if necessary): Blackening and vegetation growth.		
Deposition of sooth, discoloration, chipping of stones and pilling of plaster.		
12. Threats to the Property		
	√ NaturalNegligenceVandalismUrban Pressures	

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
10. Addio / Video	(related to rituals / performance / festivals etc.)
Reference	,
Kelelelice	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS