

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-262

SECTION I: IDENTIFICATION

1. Name

Present : Temple

Past

Other Name (if any): : Chhatri

2. Location

LONGITUDE 75°31'E **LATITUDE** 27°42'N

Address Baghela Talab, Nagada, Udaipur.

: Village (village code)

Post: Kailashpuri District: Udaipur State: Rajasthan PIN: 313602

Approach district: The Temple is situated at Nagada in Udaipur District. It

is 23km away from Udaipur bus stand. It is well

connected by regular bus services.

3. Property Type

Buildings	Religious structures	Other Structures
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	 √ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum 	Wall Gateway Pillar Others (specify) Note: What is understood as a chhatri in local area is probably reminent portion of a dilapidated temple or temple complex. The canopied corbelled roof made of stone slabs has been constructed area seven free standing stone pillars. On the pillars there are not very clear carvings of human figurer framed & geometrical patterns along with disfigured comings of kirti mukh.
Engineering structure	Open space and related structures	
Bridge Tunnel Other engineering structure	Public square Park or garden Graveyard Baolis, Well Tank Cave	

4. Property Use

		ABANDONED√/ IN USE		
Present Past	:	Temple/Religious		
5. Age (Source)				
PERIOD YEARS	:	11 th Century AD		
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : :			
6. Ownership / Level of Protection				
		SINGLE /MULTIPLE :		
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.	:			
Private	:			
Any other (Please specify)				
Name				
Address				
Phone	:			
7. Association				
WITH EVENTS				
In History	:			
In Rituals	:			
In Building Construction	:			
Any other (specify)	:			
WITH PERSONS				
Patron	:			
Architect / Engineer Any other (specify)	•			
Any other (specify)	•			
8. Statement of Significance				
Architectural				
Archaeological				
Historical Religious				
i Remonous				

Any other (specify)	:				
<u> </u>	SECTION II: DESCRIPTION				
9. Physical Description and Decorative Features					
 Context √ Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary)				
Ç	Stand in Isolation Integral part of a Landscape / Street / Complex				
 Quantification Area Dimension (L x B x H) 	:				
Number of Blocks Number of Storys	(m / cm/ feet / inch) : 01 : 01				
 Spatial Organization Orientation Plan Allocation of Spaces 	: The Temple is oriented East/West and faces the East. :				
• Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	 The exposed portion of the pillars has some carving. Along the mouldings and lintels there are bands of geographical pattern. . 				
10. Construction Technology					
Structural System Building Techniques Material of Construction	: Hindu temple architecture.: Corbelling.: Stone slabs and bolders.				
11. Condition Assessment					
In General G	ood √/ Fair good				
	Sign of Deterioration Serious Deterioration Danger of Disappearance				

In Brief (Attach extra sheet if necessary): Blackening and vegetation growth.

Major portion of stones has broken down. There are visible core cracks. Accumulation of dirt and dust in the groves and cracks are fathering. The depth of cracks and fissures. Vegetational growth and lack of general negligence.

NAME
NAME
. ,
(related to rituals / performance / festivals etc.)
(
(attach list as in page 6, in case of multiple photographs)
·
and unpublished textual details)
SECTION III: REFERENCES
Urban Pressures
√ Negligence √ Vandalism
Natural