

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-281 **SECTION I: IDENTIFICATION** 1. Name Present Mandir **Past** Other Name (if any): 2. Location **LONGITUDE** 75°31'E LATITUDE 27°42'N **Address** Sas Bahu Mandir, Nagda, Udaipur Village (village code) Post: Kailashpuri District: Udaipur State: Rajasthan PIN: 313202 Approach district The temple is situated near Sas Bahu Mandir at Nagda in Udaipur District. It is 23km away from Udaipur bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Note: It is a base of a temple built on a raised platform of stone. The base of the platform is studded with carved decorative pattern. The main structure has fallen off. Engineering structure Open space and related structures Bridge Public square Park or garden Tunnel Other engineering structure Graveyard

Baolis, Well

Tank Cave

4. Property Use

		ABANDONED√/ IN USE
Present	:	Tourist site
Past	:	Religious
		•
5. Age (Source)		
PEDIOD		45th O
PERIOD	:	15 th Century AD
YEARS	•	
Precise date of Construction		
Completion	•	
Subsequent changes	•	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on_	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)state Govt.		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	

In Building Construction : Any other (specify) :

WITH PERSONS
 Patron

Architect / Engineer Any other (specify)	: :
8. Statement of Significance	
 ✓ Architectural ✓ Archaeological ✓ Historical ✓ Religious ✓ Any other (specify) 	Hypothermal structure.
;	SECTION II: DESCRIPTION
9. Physical Description and De	corative Features
 Context Urban / Rural Setting √ Surroundings 	* Drawings (Attach extra sheet if necessary)
· ·	Stand in Isolation Integral part of a Landscape / Street / Complex
 Quantification Area Dimension (L x B x H) 	:
Number of Blocks Number of Storys	(m / cm/ feet / inch) : 01 :
 Spatial Organization Orientation Plan Allocation of Spaces 	: The Temple is oriented East/West and faces the East :
ARCHITECTURAL STYLEOrnamentationExteriors	: The base of the platform is adorned with architecheral
Interiors Movable Collections Any Other (specify)	pattern. : :
10. Construction Technology	
Structural System Building Techniques	: Raised platform of stone.
Material of Construction	: Stone and plaster

11. Condition Assessmer	nt			
In General	Good / Fair			
	Sign of Deterioration √ Serious Deterioration Danger of Disappearance			
In Brief (Attach extra sheet if necessary): blackening and vegetation growth. Badly damaged.				
12. Threats to the Propert	ty			
	√ NaturalNegligenceVandalismUrban Pressures			

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS