



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-294

SECTION I : IDENTIFICATION

1. Name

Present : Bholenath Ji ka Mandir
Past :
Other Name (if any): :

2. Location

LONGITUDE 27°42'E

LATITUDE 75°31'N

Address

Kailashpuri (Eklingi Ji) Udaipur.

: **Village (village code)**

Post: Kailashpuri

District: Udaipur

State: Rajasthan

PIN: 313602

Approach district

: The Temple is situated at Kailshpur in Udaipur District. It is 24km away from Udaipur bus stand. It is well Connected by regular bus Services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

<input type="checkbox"/>	Bridge
<input type="checkbox"/>	Tunnel
<input type="checkbox"/>	Other engineering structure

Open space and related structures

<input type="checkbox"/>	Public square
<input type="checkbox"/>	Park or garden
<input type="checkbox"/>	Graveyard
<input type="checkbox"/>	Baolis, Well
<input type="checkbox"/>	Tank
<input type="checkbox"/>	Cave

Note: The temple is built on a sloping ramp. The main body of the temple is plain and it has cubical roofing like structures. Over it there is dome roofing at the entrance and Shikar over the sanctum, respectively. The layering of subsidiary shikhars over the "moolmanjari" makes it an impressive one. However there is not much of carvings dome over it.

4. Property Use**ABANDONED / IN USE** ✓

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 14th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection**SINGLE / MULTIPLE :**

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :

Any other (specify) :

8. Statement of Significance

- | | | |
|--------------------------|---------------------|---|
| <input type="checkbox"/> | Architectural | |
| <input type="checkbox"/> | Archaeological | |
| <input type="checkbox"/> | Historical | |
| <input type="checkbox"/> | Religious | |
| <input type="checkbox"/> | Any other (specify) | : |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings** (Attach extra sheet if necessary)
Urban ✓ / **Rural Setting** : Urban setting
Surroundings : **Stand in Isolation**
Integral part of a Landscape / Street / Complex
- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)
Number of Blocks : 01
Number of Storys : 01
- **Spatial Organization**
Orientation : The Temple is oriented East/West and faces the East.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : The Amalak and the kalash are beautiful built and placed at the pinnacle.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Nagra
Building Techniques : Trabeate
Material of Construction : Stone and rubble masonry

11. Condition Assessment

In General

Good√ / Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach sheet if necessary): There is excessive blackening and discoloration on the temple also the edging and the plaster is breaking and peeling off. The affect of age and weathering is evident on the health of the temple.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input checked="" type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input checked="" type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS