

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-296 **SECTION I: IDENTIFICATION** 1. Name Present Gateway **Past** Other Name (if any): 2. Location **LONGITUDE** 27°42'E LATITUDE 75°31'N **Address** Indra Sarowar, Kailashpuri, Udaipur Village (village code) Post: Kailashpuri **District:** Udaipur State: Rajasthan **PIN**: 313602 Approach district The Gateway is situated at Kailashpuri near Eklingi Ji, in Udaipur District. It is 24km away from bus stand Udaipur. It is well connected by regular bus services. 3. Property Type Religious structures **Other Structures Buildings** Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This gate is comprises of structures two pillars as a best holding a lintel. The pillars have elaborate Bridge Public square Park or garden carving on their capital and basic Tunnel finishing on the flute. The entire Other engineering structure Graveyard Baolis, Well structure is raised on a slightly high platform. Tank Cave

4. Property Use				
		ABANDONED / IN USE√		
Present Past	:	Gateway Gateway		
5. Age (Source)				
PERIOD YEARS	:	16 th Century AD		
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : :			
6. Ownership / Level of Protection				
Public : Archaeological Survey of India / State Archaeology	:	SINGLE /MULTIPLE :		
Department / Any Other (Please specify)state Govt. Private	:			
Any other (Please specify) Name Address	:			
Phone 7. Association	:			
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS 	: : : :			
Patron Architect / Engineer Any other (specify) 8. Statement of Significance	:			
Architectural Archaeological Historical Religious Any other (specify)	:			

SECTION II: DESCRIPTION

9.	Physical Description and De	cora	tive Features	
•	Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban setting	
	Can Can an ig		Stand in Isolation Integral part of a Landscape / Street / Complex	
• H)	Quantification Area Dimension (L x B x	:	(m / cm/ feet / inch)	
	Number of Blocks Number of Storys	:01 :01		
•	Spatial Organization Orientation	:	The Gateway is oriented North/South and faces the North.	
	Plan Allocation of Spaces	:		
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : : : : : : : : : : : : : : : : : :	Basic geometrical pattern on the pillars.	
10. Construction Technology				
	Structural System Building Techniques Material of Construction		Indo-Persian and Nagara Trabeat Stone and lime plaster	
11. Condition Assessment				
	In General Go	ood√	/ Fair	
			Sign of Deterioration Serious Deterioration Danger of Disappearance	

In Brief (Attach sheet if necessary): There is Deposition of soot and pollutants in the groves of the pillar especially where the lintel has been attached. Lacks of general maintenance.

12. Tilleats to the Property	
	 √ Natural √ Negligence √ Vandalism Urban Pressures
	SECTION III: REFERENCES
13. Reference Sources (published	d and unpublished textual details)
14. Photographs	(attach list as in page 6, in case of multiple photographs)
Photo Reference	(attach list as in page o, in case of mattiple photographs)
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS