

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-323

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Dera Ka Bawari :
LONGITUDE 75°31'E	LATITUDE 27°42'N
LONGITUDE 75 STE	LAIITUDE 27 42 N
Address	Jawar Mata Mandir, Jawar, Udaipur.
	: Village (village code) Jawar.
Approach district	Post: Udaipur State: RajasthanDistrict: Udaipur PIN: 313001: The Temple is situated at Jawar in Udaipur District. It is 32km away from bus stand Udaipur. It is well connected by regular bus services.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures Other Structures Temple Wall Mosque Gateway Minar Pillar Church ✓ Monastery Bawari Stupa Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote: it is a step well cladded with rubble masonry. The well is abandoned. The area is full of vegetation growth.Park or garden Graveyard Baolis, Well Tank CaveNote: it is a step well cladded with rubble masonry. The well is abandoned. The area is full of vegetation growth.

4. Property Use	
	ABANDONED \sqrt{I} IN USE
Present Past	Not used for drinking purposeDrinking
5. Age (Source)	
PERIOD YEARS	: 16 th Century AD.
Precise date of Construction Completion Subsequent changes Destruction / Demolition	
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name	
Address Phone	
7. Association	·
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	
8. Statement of Significance	
 ✓ Architectural ✓ Archaeological ✓ Historical ✓ Religious ✓ Any other (specify) 	: cladade with stone.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

 Context Urban √/ Rural Setting Surroundings 			* Drawings (Attach extra sheet if necessary) Rural setting	
	ounounungo		Stand in Isolation Integral part of a Landscape / Street / Complex	
• H)	Quantification Area Dimension (L x B x Number of Blocks Number of Storys	: :01 :01	(m / cm/ feet / inch)	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Bawari is oriented East/West and faces the West.	
<u>AF</u> •	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections	:	Dilapidated step well	
Ar	y Other (specify)	:		

10. Construction Technology

Structural System		Step well
Building Techniques	:	English bond method.
Material of Construction	:	Stone and plaster.

11. Condition Assessment

In General

Good / Fair√ Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary): blackening and vegetation growth.

Dilapidated

12. Threats to the Property

 Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attack list as in page C in some of multiple shots more bay)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS