



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/UDP-335

SECTION I : IDENTIFICATION

1. Name

Present : Hanuman ji Ka Mandir

Past :

Other Name (if any): :

2. Location

LONGITUDE 75° 31' E

LATITUDE 27°42' N

Address

Rajputo ka mohalla, Gogunda

Village (village code) Gogunda
Post: Gogunda **District:** Udaipur
State: Rajasthan **PIN:** 313705

Approach

: The Temple is situated at Gogunda in Udaipur District. It is 3km away from Udaipur bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note This is an old temple which has an influence of imperial mughal architecture. It has a dome which is surmounted by an inverted lotus type of pinnacle. The door lintel and Dwar-sakha of the main shrine are embellished with decorative floral designs. There are also beautiful paintings

of Hindu Gods and goddesses.
The main shrine has a glossy
image of the deity which is painted
with red colour. Glazed marble

4. Property Use

ABANDONED/ IN USE ✓

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 16th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology :
Department / Any Other (Please :
specify) :
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	: Dome having an inverted lotus type of pinnacle.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- | | | |
|------------------------------|--|--|
| Context | | * Drawings (Attach extra sheet if necessary) |
| Urban / Rural Setting | | Rural Setting |
| Surroundings | | Stand in Isolation |
| | | Integral part of a Landscape / Street / Complex |

- | | | |
|-------------------------------|----|-----------------------|
| Quantification | | |
| Area Dimension (L x B x H) : | | (m / cm/ feet / inch) |
| Number of Blocks : | 01 | |
| Number of Storys : | 01 | |

- | | | |
|-----------------------------|--|--|
| Spatial Organization | | |
| Orientation : | The Temple is oriented East/West and faces the West. | |
| Plan : | | |
| Allocation of Spaces : | | |

ARCHITECTURAL STYLE

- | | | |
|------------------------------|---|--|
| Ornamentation | | |
| Exteriors : | It has a foliated arch opening. The gate and windows have ornamented iron-grills. | |
| Interiors : | Glossy image of the deity. | |
| Movable Collections : | | |
| Any Other (specify) : | | |

10. Construction Technology

- | | | |
|---------------------------------|---|---------------------------|
| Structural System | | Indo-Parisian |
| Building Techniques | : | Brick masonry |
| Material of Construction | : | Stone, brick, marble etc. |

11. Condition Assessment

In General

Good / Fair Good

- | | |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

Note – Plaster is peeling off.

In Brief (Attach extra sheet if necessary):

Blackening of the dome.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input type="checkbox"/> | Natural |
| <input checked="" type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS

