

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/UDP-348 **SECTION I: IDENTIFICATION** 1. Name Present Mahadev Mandir Ka Bawari Past Other Name (if any): 2. Location LONGITUDE 75° 31' E **LATITUDE** 27°42' N **Address** Mahadev Bawari, Gogunda. Village (village code) Post: Gogunda **District:** Udaipur State: Rajasthan **PIN:** 313705 Approach The Bawari is situated at Gogunda in the Udaipur District. It is 35km away from bus stand Udaipur. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Wall Palace Temple Fort Mosque Gateway Citadel Minar Pillar Govt. building Others (specify) Church Railway station Monastery Defence building Stupa Tomb, Mausoleum Industrial building Other public buildings Residential building Engineering structure Open space and related It is a step well. There is a Note structures deposition of dirty and stagnant Bridge Public square water. There are canopied chhatri Park or garden on either side of the well. The well Tunnel can be approached by means of Other engineering structure Graveyard flight of steps on three sides. Baolis, Well Tank Cave

4. Property Use		
	ABANDONED √/ IN USE	
Present Past	Not used for drinking purposeDrinking water	
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes	: 11 th Century AD : :	
Destruction / Demolition	:	
6. Ownership / Level of Protection		
	SINGLE /MULTIPLE :	
India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address	: : : :	
Phone	:	
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: : : : : : :	
8. Statement of Significance		
 ✓ Architectural Archaeological Historical Religious Any other (specify) 	Chhatries on either side of the well.	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

Urban / Rural Setting Surroundings

* **Drawings (**Attach extra sheet if necessary)

Rural Setting

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension $(L \times B \times H)$:

(m / cm/ feet / inch)

Number of Blocks : Number of Storys :

Spatial Organization

Orientation : The well can be approached by means of flight of steps

on three sides.

Plan

Allocation of Spaces

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Interiors :

Movable Collections : Any Other (specify) :

10. Construction Technology

Structural System : Indo-Persian
Building Techniques : Brick masonry
Material of Construction : Brick and stone.

11. Condition Assessment	11. Condition Assessment		
In General	Good / Fair Good		
	√ Sign of DeteriorationSerious DeteriorationDanger of Disappearance		
Note – Plaster is peeling off.			
In Brief (Attach extra sheet if necessary):			
Peeling of plaster, blackening of the wall and discoloration.			
12. Threats to the Property			
	√ Natural		
	√ Negligence		
	√ Vandalism		
	√ Urban Pressures		

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS