

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments Serial No.: RJ/UDP-355 **SECTION I: IDENTIFICATION** 1. Name Present Bairo Mandir **Past** Other Name (if any): 2. Location LONGITUDE 75° 31' E **LATITUDE** 27°42' N Address Jaswantgarh, Udaipur Gogunda Village (village code) Post: Nadesma **District:** Udaipur State: Rajasthan **PIN: 313708 Approach** The Temple is situated at Jaswantgarh in the Udaipur District. It is 43km away from bus stand Udaipur. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures **Other Structures** Temple Palace Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related This is a temple having structures painted dome surmounted by an inverted lotus type of pinnacle. Bridge Public square The interior of the temple has Tunnel Park or garden been renovated. The main shrine Other engineering structure Graveyard has images of deity and sub-Baolis, Well ordinate deities.

Tank Cave

| 4. Property Use | | |
|------------------------------------|----|--|
| | | ABANDONED / IN USE√ |
| Present | : | Religious |
| Past | : | Religious |
| | | · · |
| 5. Age (Source) | | |
| PERIOD | | 19 th Century AD |
| YEARS | : | 10 Contary N.D |
| Precise date of Construction | : | |
| Completion | : | |
| Subsequent changes | : | |
| Destruction / Demolition | : | |
| 6. Ownership / Level of Protection | on | |
| • | | SINGLE /MULTIPLE : |
| | : | |
| India / State Archaeology | | |
| Department / Any Other (Please | | |
| specify) | | |
| Private Any other (Please specify) | • | |
| Name | • | |
| Address | : | |
| Phone | : | |
| 7. Association | | |
| | | |
| WITH EVENTS | | |
| In History In Rituals | • | |
| In Building Construction | : | |
| Any other (specify) | : | |
| WITH PERSONS | | |
| Patron | : | |
| Architect / Engineer | : | |
| Any other (specify) | : | |
| | | |
| 8. Statement of Significance | | |
| √ Architectural | | |
| Archaeological | | |
| Historical Religious | | |
| Any other (specify) | : | Dome having inverted lotus type of pinnacle. |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Urban / Rural Setting Surroundings

etting Rural setting

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension $(L \times B \times H)$:

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Storys : 01

Spatial Organization

Orientation : The Temple is oriented East/West and faces the East.

Plan

Allocation of Spaces :

ARCHITECTURAL STYLE

Ornamentation

Exteriors : The dome of the temple has thick coat of lime-plaster.

Interiors

Movable Collections

Any Other (specify) :

10. Construction Technology

Structural System : Indo-Perisian

Building Techniques : Imperial Mughal style and modern style.

Material of Construction : Brick and stone.

| 11. Condition Assessment | | |
|---|---|--|
| In General | Good / Fair Good | |
| | ✓ Sign of DeteriorationSerious DeteriorationDanger of Disappearance | |
| Note – Plaster is peeling off. | | |
| In Brief (Attach extra sheet if necessary): | | |
| Blackening of the walls. | | |
| 12. Threats to the Property | | |
| | √ Natural √ Negligence √ Vandalism Urban Pressures | |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs | |
|-------------------------|---|
| | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference | |
| CAPTION | |
| CAPTION | |
| 15. Audio / Video | |
| | (related to rituals / performance / festivals etc.) |
| Reference | |
| DESCRIPTION | |
| 16. Maps/Plans/Drawings | |
| | |
| | |
| 17. Listers | |
| NAME | NAME |
| | |
| 18. Reviewers | |
| NAME | NAME |
| | |
| COMMENTS | COMMENTS |