

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-360

	SECTION I : IDENTIFICATION
1. Name	
Present	: Parashaw Nath Jee Ka Mandir.
Past Other Name (if any):	
2. Location	
LONGITUDE 75°31'E	LATITUDE 27°42'N
Address	Rishabhdev Udaipur.
	: Village (village code)
	Post: Rishabhdev.District: UdaipurState: RajasthanPIN: 313802
Approach district	: The Temple is situated at Rishabhdev in Udaipur District. It is 62km away from Udaipur bus stand. It is well connected by regular bus services.
3. Property Type	
Buildings	Religious structuresOther Structures√TempleWall

Dunungs	_	nengious siruciures		
Palace		Temple		Wall
Fort		Mosque		Gateway
Citadel		Minar		Pillar
Govt. building		Church		Others (specify)
Railway station		Monastery		
Defence building		Stupa		
Industrial building		Tomb, Mausoleum		
Other public buildings		-		
Residential building				
Residential building				
Engineering structure	-	pen space and related ructures		te: This is a Nagara style of nple rich in architecture
0	-	-	ten	3 ,
Engineering structure	-	ructures	ten em	nple rich in architecture
Engineering structure Bridge	-	r uctures Public square	ten em ten and	nple rich in architecture bellishments. The Shikar of the nple has multiple projections d recesses. The shikhara is
Engineering structure Bridge Tunnel	-	ructures Public square Park or garden	ten em ten and cro	nple rich in architecture bellishments. The Shikar of the nple has multiple projections d recesses. The shikhara is woned by an "Amalka". The
Engineering structure Bridge Tunnel	-	ructures Public square Park or garden Graveyard	ten em ten and cro ma	nple rich in architecture ibellishments. The Shikar of the nple has multiple projections d recesses. The shikhara is wined by an "Amalka". The in shrine of the temple has
Engineering structure Bridge Tunnel	-	ructures Public square Park or garden Graveyard Baolis, Well	ten em ten and cro ma	nple rich in architecture bellishments. The Shikar of the nple has multiple projections d recesses. The shikhara is woned by an "Amalka". The

painted with colorful floral pattern. The image of deity is placed on high raised platform. The Small images of subordinate deities are placed on either side of the main

4. Property Use

	ABANDONED / IN USE $$
	:
	—
Present	: Religious
Past	: Religious
5. Age (Source)	
PERIOD	: 14 th Century AD
YEARS	:
Draging data of Construction	
Precise date of Construction	
Completion	
Subsequent changes	
Destruction / Demolition	
6 Ownership / Level of Drotest	on
6. Ownership / Level of Protection	
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)state Govt.	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	
In Rituals	:
	:
In Building Construction	
Any other (specify)	-
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:

8. Statement of Significance

√ 	Architectural Archaeological Historical Religious	Т	he shikhara has multiple ornate projections and recesses.
	Any other (specify)	:	
	<u> </u>	SEC	TION II: DESCRIPTION
9.	Physical Description and De	cora	ative Features
•	Context Urban / Rural Setting√ Surroundings		* Drawings (Attach extra sheet if necessary) Rural Setting
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / om/ foot / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation	:	The Temple is oriented North/South and faces the North.
	Plan Allocation of Spaces	:	
<u>AF</u> •	CHITECTURAL STYLE Ornamentation Exteriors Interiors	:	It has a number of ornate projections and recesses. The main shrine has foliated arch opening with floral
	Movable Collections	:	designs.
An	y Other (specify)	:	
10	. Construction Technology		

Structural System	:	Negara style of temple.
Building Techniques	:	Arcuate system.
Material of Construction	:	Stone, iron-grills, marbles, brick

11. Condition Assessment

In General

Good $\sqrt{7}$ Fair good

\checkmark	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well- maintained

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attach list op in page 6 in page of multiple photographe)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
	COMMENTS
COMMENTS	