

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/UDP-361

1. Name	SECTION I: IDENTIFICATION	
Present	: Well	
Past Other Name (if any):	:	
2. Location		
LONGITUDE 75° 31' E	LATITUDE 27°42' N	
Address	Jaswantgarh, Udaipur	
Annuarah	: Village (village code) Post: Nadesma State: Rajasthan	Gogunda District: Udaipur PIN: 313708
Approach		Jaswantgarh in the Udaipur from Udaipur bus stand. It is ar bus services.
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Temple	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures in Public square for	lote: It is a dilapidated well. An ron-wheel is attached to the well or fetching water. The well is vithout any enclosure wall.

4. Property Use

ABANDONED √/ IN USE :

Present	:	Drinking
Past	:	Drinking

5. Age (Source)

PERIOD	:	19 th Century AD
YEARS	:	-
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of	1
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	
Address	
Phone	

7. Association

• WITH EVENTS In History In Rituals In Building Construction : Any other (specify) WITH PERSONS • Patron Architect / Engineer Any other (specify)

8. Statement of Significance

\checkmark	Architectural		
	Archaeological		
	Historical		
	Religious		
	Any other (specify)	:	Rubble masonry

:

:

:

:

:

:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Rural setting
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / om / fo ot / in ob)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch)
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Well is oriented North/South and faces the South.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	::	It is a well having iron-wheel.

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Rubble masonry
Material of Construction	:	Brick, stone, plaster etc.

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

Note – Plaster is peeling off.

In Brief (Attach extra sheet if necessary):

Dilapidated.

12. Threats to the Property

	Natural
\checkmark	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME